



FORZA AUTOHAUS PTE LTD

39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS
 SINGAPORE 737856
 TEL: 62781889 EMAIL: ENQUIRY@FORZAAUTO.SG
 CO./GST REG: 201833292C

ESTIMATE

LEON TEO
 BLK 15 MARINE TERRACE #12-02
 Singapore 440015
 Contact No. : 92329611

Code : E22100011
 Date In : 27/10/2022
 Vehicle No. : SGF44J
 Model : B.M.W. , 520I 2.0L AT D
 Chassis No. : WBAXG12040DX53193

Parts and Labour Assessment

Description	Qty	Unit Price	Amount
Parts & Services			
FRONT FENDER RH (REPAIR)	1.00	0.00	0.00
FRONT FENDER INNER SHIELD RH <i>X NN</i>	1.00	172.50	172.50
FRONT BUMPER SENSOR RH <i>- Mis</i>	1.00	232.40	232.40
FRONT REINFORCEMENT BEAM <i>X</i>	1.00	452.40	452.40
FRONT LOWER ARM RH <i>X</i>	1.00	252.10	252.10
FRONT KNUCKLE ARM RH <i>X</i>	1.00	371.30	371.30
FRONT WHEEL HUB RH <i>X</i>	1.00	621.40	621.40
FRONT ABSORBER RH <i>X</i>	1.00	372.10	372.10
FRONT HEADLAMP CONTROL MODULE RH <i>?</i>	1.00	532.40	532.40
FRONT BONNET <i>- BT</i>	1.00	1,523.20	1,523.20
FRONT HEADLAMP RH <i>- COA</i>	1.00	2,235.20	2,235.20
FRONT BUMPER TOW COVER	1.00	62.30	62.30
FRONT BUMPER NOZZLE SPRAY COVER <i>- 4 Mis</i>	1.00	74.30	74.30
FRONT BUMPER NOZZLE SPRAY	1.00	152.40	152.40
FRONT BUMPER RETAINER <i>X BT - Cut</i>	1.200	154.20	308.40
FRONT BUMPER <i>- R</i>	1.00	1,423.20	1,423.20
		Subtotal Before Discount S\$	8,785.60
		0% Discount S\$	439.25
		Subtotal S\$	8,346.35
FRONT BUMPER CLIPS SET	1.00	30.00	30.00
		Subtotal S\$	30.00
		Parts & Services Total S\$	8,376.35
Labour			
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING	1.00	0.00	0.00
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1.00	1,000.00	1,000.00
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	1.00	1,000.00	1,000.00
		Subtotal S\$	2,000.00
		Labour Total S\$	2,000.00

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental cost must be surveyed and is subject to final approval from insurance Co.

Acknowledged by Reparer
 Date:

*5 Days.
 Lumpsum repair
 After repair photos
 Gue Guan - 82 880282
 28/10/22*

Parts & Services Total S\$ 8,376.35
Labour Total S\$ 2,000.00
Grand Total S\$ 10,376.35