

**DMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO **SHA4061Y**  
 MAKE **REG.30.10.2019**  
 MODEL **: HYU IONIQ G3**

DATE **27.10.2022**

**CHIANG/ INT. INCOME**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH			na X \$55.80
1	FRONT BUMPER			na X \$481.10
1	FRONT BUMPER GRILLE RH			cut X \$186.50
1	FRONT BUMPER MOULDING CENTRE UPPER			X \$368.50
1	FRONT DAY LIGHT RH			na X \$642.50
1	FRONT FENDR SHIELD RH			X \$164.70
1	HEAD LAMP RH			X \$2,110.30
1	FRONT FENDER RH			bt X \$588.80
1	FRONT FENDER EMBLEM			cut \$26.60
1	FRONT WHEEL COVER			cut \$346.40
	<b>SUB TOTAL</b>			<b>\$4,971.20</b>
	<b>20.00% DISCOUNTED TOTAL</b>		1629.40	<b>\$994.24</b>
			1303.50	<b>\$3,976.96</b>
1	FRONT FENDER ADVERTISEMENT		100	cut \$100.00
				<b>\$100.00</b>
	<b>Labour Charge</b>			
	Panel Beating		350	\$700.00
	Spray Paint		850	\$600.00
	Check lighting			X na \$60.00
	Towing Fee			X na \$60.00
	<b>TOTAL LABOUR</b>		2253.50	<b>\$1,420.00</b>
	<b>ESTIMATE TOTAL</b>		4541.800	<b>\$5,496.96</b>
			2 days	
			*	

*Tanpin 9741 5747  
 'wp' 27/10/22 @ 430pm  
 as many after repair  
 Tanpin @ (Khandowun  
 2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.