

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHB3640C

MAKE/REG 10.08.2018

MODEL : HYUNDAI IONIQ G2

DATE 27.10.2022

CHIANG/INCOME				
Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	TAIL LAMP LH		ana	\$935.40
1	REAR FENDER LH		RP	\$1,768.30
1	REAR DOOR HANDLE LH		R cost	\$108.40
1	FRONT WING MIRROR LH		bur	\$1,391.70
		SUB TOTAL		2327.10
		LESS 20%		\$840.76
		DISCOUNTED TOTAL		<u>1861.68</u> <u>\$3,363.04</u>
1	FRONT DOOR ADVERTISEMENT		int	\$100.00
1	REAR DOOR ADVERTISEMENT		out	\$100.00
1	FRONT DOOR CITY CAB STICKER		rep	\$75.00
1	REAR DOOR COMFORT APP STICKER		rep	\$80.00
1	PETROL STICKER		rep	\$25.00
1	REAR FENDER ADVERTISEMENT		int	\$100.00
				<u>\$462.00</u>
	Labour Charge			
	Panel Beating		525	\$1,225.00
	Spray Painting Charge		850	\$900.00
	Remove/refix Upholstery		nmk	\$90.00
	Check Wiring		70	\$60.00
		TOTAL LABOUR	1405	<u>\$2,275.00</u>
		ESTIMATE TOTAL	3728.68	<u>\$61,000.04</u>
			4593000	6100.04
			3 days *	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanj Mi 99415949
 WP 29/10/22 2 430 pm
 1/3 ready for repair
 Tanj Mi C LKK auto consul
 3 days