

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Faiz Rosli

Date: 01 Nov 2022

Preliminary Advice

Insured : GBH2363H

Vehicle No

TP Vehicle : SGD3005M
No

Accident Date : 26/10/2022

Make : TOYOTA VIOS

Assignment Date : 28/10/2022

Date of : 28/10/2022

Est. Duration of : 3
Repair

Inspection

Inspection At : IMPERIUM AUTOMOTIVE - KAKI BUKIT (HQ)
25 KAKI BUKIT ROAD 4, #01-49 SYNERGY@KB
SINGAPORE 417800

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 12,237.55

Revised Amount :S\$ 3,628.40

Check Items (Estimated) :S\$ 0.00

Total :S\$ 3,628.40

Lump Sum Repair :S\$ 2,900.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.