LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

Singapore 038988

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 31 Oct 2022

Preliminary Advice

Vehicle No: SJX6414EAccident Date: 25/10/2022Make: TOYOTA VIOSPolicy No.: DMPG22007334

Assignment Date : 28/10/2022 Excess : S\$0.00

Date of Inspection : 28/10/2022 Est. Duration of Repair : 09 DAYS

Inspection At : LKT GROUP PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,439.00
Revised Amount	:S\$	7,819.26
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,819.26

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 26,000.00 COE / PARF Rebate :S\$ 8,748.00

Salvage Value :S\$

Margin for Repair :S\$ 17,252.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.