



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22006903/Acy3e2-1	
			Date: 15/11/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBF 380Y	Veh. Inspected	GBH 9503R
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/026047	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	27/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	OPEL VIVARO	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	W0VF7G606JV601901	Colour	BLACK
	Odometer	58275 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16C	GRENLANDER	6 mm
	L/H Front Tyre	205/65 R16C	GRENLANDER	6 mm
	R/H Rear Tyre	205/65 R16C	GRENLANDER	6 mm
	L/H Rear Tyre	205/65 R16C	GRENLANDER	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	18/07/2022	Inspection Date	31/10/2022
	Survey held at	BOOST AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	