


PRS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP ☐ / S / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s A-TEC AUTO
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$61k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ1362D Yr Regn: 29 Nov 2016
 Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: HONDA / SHUTTLE 1.5 c.c. 1496
 Colour Black A/C: Insured / Std / NI / NA
 Sp. Reading — T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GP71043538
 Gen. Cond ☒ Good ☐ Fair / Poor / Burnt
 Steering: ☒ Inorder ☐ Jammed / Leaked / Burnt or
 Brake: ☒ Inorder ☐ Jammed / Leaked / Burnt or
 Modi: ☒ Nil ☐ S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR ☐ SUMI /
 TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. _____		D.O.I. <u>15-03-2022</u>	

Survey held at W/S 5PM

Des. of Damages : Frt / Rear / ☒ O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$4000 \$5000
17/03/23	submit lump sum: \$4850 and 7 days (red, \$15450, 76%)
	SUBMIT PRS REPORT

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) 17/03/23

Date/Time, File Return to?

2)

Days Of Repair: 5 7

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)
☐ : W/Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ SI

Photos

Other:

TOTAL

Report Filed:

Lump Sum / MPB: