

COMFORTDELGRO ENGINEERING PTE LID

REPAIR ESTIMATE*

VEHICLE NO SH9767U

20.10.2022

MAKE REG 23.08.2017

MODEL PRIUS G4

CHIANG /CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER ASSY			\$586.18
10	FRONT BUMPER CLIP			\$2.20
1	FRONT BUMPER BRACKET LH			\$82.30
1	FRONT RADIATOR GRILLE EMBLEM			\$88.00
1	FRONT BUMPER HOLE LH			\$28.38
1	FRONT HEADLAMP ASSY LH			\$2,637.60
1	FRONT FOG LAMP LH			\$920.00
1	FRONT WING MIRROR COVER LH			\$141.90
1	FRONT WING MIRROR ASSY LH			\$1,390.10
1	FRONT WHEEL COVER LH			\$189.60
1	FRONT FENDER LH			\$1,111.93
1	FRONT FENDER SHIELD LH			\$198.50
1	FRONT FENDER EMBLEM LH			\$86.20
	SUB TOTAL			\$7,462.89
	25.00%			\$1,865.72
	DISCOUNTED TOTAL			\$5,597.16
1	FRONT DOOR ADVERTISEMENT			\$100.00
1	FRONT FENDER ADVERTISEMENT			\$100.00
				\$200.00
	Labour Charge			
	Panel Beating			\$700.00
	Spray Painting Charge			\$600.00
	Reset front wheel alignment			\$60.00
	TOWING FEE			\$60.00
	Check Wiring & Lighting			\$60.00
	TOTAL LABOUR			\$1,480.00
	ESTIMATE TOTAL			\$7,277.16
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NGL LKA
 25/10/2022 1710 HRS
 LIS
 3 Days
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS