



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/10/2022
Vehicle Reg. No.:	YQ2843K	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (M)	Vehicle Reg. Date:	08/12/2020
Vehicle Colour:	WHITE	Chassis No:	FEB21EA35176
Engine No:	4P10E39235		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	2,990.90
Miscellaneous Items	280.00
Labour	1,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	4,800.90
+ GST 7.00% (\$)	336.06
Nett Amount (\$)	5,136.96

This claim is handled by: BRIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS		
Reference		
Part Source:	(Last Synchronised: 28 Oct 2022)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEN (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Mova Automotive Pte Ltd/YQ2843K/28/10/2022 18:32	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH CORNER PANEL	0.00	0.00	*340.00 F
2	1		*SIGNAL LAMP LH	0.00	0.00	*240.00 F
3	1		*HEADLAMP LH	0.00	0.00	*400.00 F
4	1		*HEADLAMP LOWER TRIM, LH	0.00	0.00	*50.00 F
5	1		*HEADLAMP LOWER TRIM CLIPS	0.00	0.00	*4.00 F
6	1		*FRONT BUMPER	0.00	0.00	*700.00 F
7	1		*FRONT BUMPER BRKT	0.00	0.00	*150.00 F
8	1		*BUMPER CORNER LH	0.00	0.00	*250.00 F
9	1		*SIDE STEP LH	0.00	0.00	*400.00 F
10	1		*BUMMY COVER LH	0.00	0.00	*140.00 F
11	1		*BLUETEC DECAL	0.00	0.00	*45.00 F
F=Franchise part.						
Sub Total (\$\$)						2,719.00
+ Margin on L,N Items 10.00% (\$\$)						271.90
Total Parts (\$\$)						2,990.90

Mova Automotive Pte Ltd/YQ2843K/28/10/2022 18:32. Not valid without Reference section. Generated using Merimen e-Claims IEAS	
---	--

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	COMPANY GRAPHIC STICKER	280.00
Sub Total (\$\$)			280.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPLACE DAMAGES PART & REALIGN A-PILLAR	New	450.00
2	TO SPRAY PAINT ON FRONT BUMPER & LH FRONT DOOR	New	450.00
3	TO CALIBRATE FRONT BUMPER, RADAR SYSTEM (ADAS)	New	450.00
4	TO CHECK FOR & RECTIFY WIRING FAULTS. TO CONDUCT DIAGNOSTICS CHECK AFTER REPAIR	New	180.00
Gross Labour Cost (\$\$)			1,530.00

Mova Automotive Pte Ltd/YQ2843K/28/10/2022 18:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >