



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010778/Kvy3m4	
			Date: 29/12/2022	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBF 3748B
	Policy No.	D22MTPCVE002416	Coverage (\$)	0.00
	Claim No.	CMTD2203885/MYE	Excess (\$)	600.00
	Assign From	MELVIN YE	Assign Date	31/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR (M)	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JN1SC2F24Z0858963	Colour	BLUE
	Odometer	165173 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
	R/H Rear Tyre	155 R12X8 (D)	TRIANGLE	8/8 mm
	L/H Rear Tyre	155 R12X8 (D)	TRIANGLE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/10/2022	Inspection Date	31/10/2022
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A)THE MARKET VALUE IS S\$46,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	