



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 5610B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
4	UV TREATED GRP BOARD FOR THE EXTERIOR AND INTERIOR OF DOORS @\$500.00 (CONSISTENT)	BENT (2 PCS ONLY)	2,000.00	1,000.00
2	100MM THICKNESS EXTRUDED XPS INSULATION FOAM WITH A MIN.DENSITY OF 40KG/M3 BETWEEN THE EXTERIOR AND INTERIOR @\$720.00(CONSISTENT)	NECESSARY (1 PCS ONLY)	1,440.00	720.00
2	4FT HEIGHT ALUMINIUM CHECKER SKIRTING FOR THE INTERIOR OF DOORS @\$480.00 (CONSISTENT)	NECESSARY (1 PCS ONLY)	960.00	480.00
15	SEALANT TUBE @\$25.00 (CONSISTENT)	NECESSARY (8 PCS ONLY)	375.00	200.00
4	STAINLESS STEEL DOOR HINGES @\$280.00 (CONSISTENT)	TO REPAIR SEE LABOUR	1,120.00	-
2	STAINLESS STEEL RECESS LOCKS C/W KEYS @\$320.00 (CONSISTENT)	DISTORTED / CUT (1 PCS ONLY)	640.00	320.00
8	LENGTH DOOR RUBBER GASKETS @\$95.00 (CONSISTENT)	NECESSARY (4 PCS ONLY)	760.00	380.00
3	DOOR RUBBER STOPPER @\$98.00(CONSISTENT)	DENTED / TORN	294.00	294.00
1	SET STAINLESS STEEL DOOR HOLDER (CONSISTENT)	NECESSARY	90.00	90.00
			7,679.00	3,484.00
<b>SPECIAL NETT ITEMS</b>				
1	SUPPLY AND PAINT LOGO AT DOORS (SN) (CONSISTENT)	NECESSARY	400.00	300.00
			400.00	300.00
<b>LABOUR</b>				
TO SUPPLY LABOUR TO-REMOVE ,REFIX AND TO RENEW AFFECTED PARTS. REVERTING ,ADJUST AND REALIGNMENT DOORS.INCLUSIVE OF THE REPAIR OF STAINLESS STEEL DOOR HINGES .			2,400.00	1,100.00
			2,400.00	1,100.00
<b>GRAND TOTAL</b>			<b>10,479.00</b>	<b>4,884.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,884.00</b>

Report Ref No. CC4/ASM22010805/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.