

REF: AGZ/22010812/kw



BCC AUTOMOTIVE PTE LTD

BLK 1 SIN MING IND. ESTATE SECTOR C
#101/103/105 SINGAPORE 575636
Tel: +65 6552 5588 Fax: +65 6552 7750
Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : SMQ17180

Quotation Date : 2022-10-28

Vehicle Reg No : SME273Z
Name : BUDGET DIRECT INSURANCE
Address : 1, 1, SINGAPORE, 1
Contact No :
Email :

Make & Model : MERCEDES BENZ - E200 AMG LINE
AUTO
Chassis No : WDD2130422A540646
Mileage : 42058 KM
Officer-In-Charge : KARSENG
Page : 1 of 2

Not Authorized

Penny B4point

5 days

810,282.60

No	Description	Unit Price	Qty	Disc (%)	Amount	
1	BOOT LID 2293	2350.00	1.00	10.00	2,115.00	✓
2	BOOT LOCK	500.00	1.00	10.00	450.00	X
3	BOOT CATCH	215.00	1.00	10.00	193.50	X
4	REAR BUMPER 1874	2150.00	1.00	10.00	1,935.00	✓
5	REAR BUMPER TOW COVER 79	190.00	1.00	10.00	171.00	✓
6	REAR BUMPER LH BRACKET	160.00	1.00	10.00	144.00	✓
7	REAR BUMPER RH BRACKET	160.00	1.00	10.00	144.00	✓
8	REAR BUMPER CENTER BRACKET 258	365.00	1.00	10.00	328.50	✓
9	REAR LOWER SPOILER 674	830.00	1.00	10.00	747.00	✓
10	REAR LOWER SPOILER RH EXHAUST 410	925.00	1.00	10.00	832.50	✓
11	REAR LOWER SPOILER LH EXHAUST 410	925.00	1.00	10.00	832.50	✓
12	REAR REVERSE SENSOR C234	360.00	1.00	10.00	648.00	✓
13	REAR REINFORCEMENT 830	830.00	1.00	10.00	747.00	✓
14	REAR END PANEL OUTER 1604	750.00	1.00	10.00	675.00	✓
15	REAR END PANEL INNER	820.00	1.00	10.00	738.00	X
16	LABOUR CHARGES TO TRANSFER REAR BOOT LID WIRE HARNESS				300.00	601
	TO PANEL BEAT ON THE AFFECTED AREA	2000.00	1.00		2,000.00	701
	TO SPRAY PAINT ON THE AFFECTED AREA	2000.00	1.00		2,000.00	901

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

REF: AGZ/ 2201081211



BCC AUTOMOTIVE PTE LTD
 BLK 1 SIN MING IND. ESTATE SECTOR C
 #101/103/105 SINGAPORE 575636
 Tel: +65 6552 5588 Fax: +65 6552 7750
 Email: enquiry@bcc.sg Website: enquiry@bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ17180**
 Quotation Date : **2022-10-28**

Vehicle Reg No : SME273Z
 Name : BUDGET DIRECT INSURANCE
 Address : 1, 1, SINGAPORE, 1
 Contact No :
 Email :

Make & Model : MERCEDES BENZ E200 AMG LINE
 Chassis No : WDD2130422A540646
 Mileage : 42058 KM
 Officer-In-Charge : KARSENG
 Page : 2 of 2

No	Description	Unit Price	Qty	Disc (%)	Amount
19	TO REMOVE THE REAR TRIM BOARD TO FACILITATE REPLACE THE REAR END PANEL	300.00	1.00		300.00

602

Sub-Total : 15,301.00
 Add GST 7% : 1,071.07
Estimated Total Amt (SGD) : 16,372.07

NOTE:

This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.
 If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to job performed

CUSTOMER'S AUTHORISATION

I agree to this quotation and hereby authorize to proceed with the above listed repairs.

CUSTOMER'S SIGNATURE _____

(& Co's Stamp, WHERE NECESSARY)



BCC AUTOMOTIVE PTE LTD
 BLK 1 SIN MING IND. ESTATE SECTOR C
 #101/103/105 SINGAPORE 575636
 Tel: +65 6552 5588 Fax: +65 6552 7750
 Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ17196**
 Quotation : **2022-11-03**
 Date

Vehicle Reg No : SME273Z
 Name : BUDGET DIRECT INSURANCE
 Address : 1, 1, SINGAPORE, 1
 Contact No :
 Email :

Make & Model : MERCEDES BENZ - E200 AMG LINE
 AUTO
 Chassis No : WDD2130422A540646
 Mileage : 42058 KM
 Officer-In-Charge : KARSENG
 Page : 1 of 1

No	Description	Unit Price	Qty	Disc (%)	Amount
1	REAR END PANEL TOP GARNISH	280.00	1.00	10.00	252.00
2	REAR RH BUMPER REFLECTOR	88.00	1.00	10.00	79.20
3	REAR BUMPER UNDER BRACKET	160.00	1.00	10.00	144.00

Sub-Total : 475.20
 Add GST 7% : 33.26
Estimated Total Amt (SGD) : 508.46

NOTE:

This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.
 If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to job performed

CUSTOMER'S AUTHORISATION

I agree to this quotation and hereby authorize to proceed with the above listed repairs.

CUSTOMER'S SIGNATURE _____

(& Co's Stamp, WHERE NECESSARY)