



Your Ref: 202222007511

Date: 08th March 2023

Our Ref: CS6/AIS22010820/Evy3m4

M/s Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SMA 2598U ACCIDENT ON 17/10/2022

We thank you for your instruction on 31/10/2022.

The following vehicle information was recorded:

Registration Number	: SMA 2598U
Make & Model	: Toyota Harrier M Grade
Chassis Number	: JTEZB3GH70J002123
Year of Registration	: 2018
Engine Capacity	: 1998 cc

1. The vehicle sustained damages at the rear o/s portion. (Details see photographs enclosed)
2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.