



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	0	Date of Loss:	17/10/2022
Vehicle Reg. No.:	SMA2598U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	OW KIM LENG, VINCENT		
Make/Model:	TOYOTA HARRIER, 2.0 (A)	Vehicle Reg. Date:	31/05/2018
Vehicle Colour:	Silver		
Engine No:	8ARZ122484	Chassis No:	JTEZB3GH70J002123
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	1,694.00
Miscellaneous Items	0.00
Labour	850.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,544.00
+ GST 7.00% (S\$)	178.08
Nett Amount (S\$)	2,722.08

This claim is handled by: **KEONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR FENDER AIR VENT RH - TO CHECK	-
2	1	REAR FENDER RH - TO REPAIR	-
Sub Total (\$\$)			0.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR REAR FENDER RH, REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREA	New	350.00
2	TO SPRAY REAR FENDER RH, REAR BUMPER & AFFECTED AREAS	New	500.00
Gross Labour Cost (\$\$)			850.00

Mova Automotive Pte Ltd/SMA2598U/31/10/2022 13:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >