

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	Ref:	CS/AGI22010830/Aqy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	20/12/2022	
			C	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMA 5366C	Veh. Inspected		SLA 8216U	
	Policy No.	P10176444R03	Coverage (\$)		0.00	
	Claim No.	C10018320/CD	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		31/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA BIANTE	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JM6CC1071G0109182	Colour		BLUE	
	Odometer	75881 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	KAPSEN		6 mm	
	L/H Front Tyre	205/60 R16	KAPSEN		6 mm	
	R/H Rear Tyre	205/60 R16	KAPSEN		6 mm	
	L/H Rear Tyre	205/60 R16	KAPSEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/10/2022	Inspection Date		31/10/2022	
	Survey held at	Survey held at TWINCAR AUTOMOTIVE PTE LTD  2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	1-)	Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: