

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAI	NCE PTE LTD	Ref:	CS/LIP22010834/Aqy3e2	
	51 CLUB STREET LIBERTY HOUSES	, #03-00 SINGAPORE 069428	Date:	30/03/2023	
			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 8213E	Veh. Inspected	SLX 67P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	IVS22/1856-	Excess (\$)	0.00	
	Assign From	TED SEAH	Assign Date	31/10/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 520I	c.c	1997	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.	WBAXG12030DX53489	Colour	BLACK	
	Odometer	212322 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/55 R17	PIRELLI	6 mm	
	L/H Front Tyre	225/55 R17	PIRELLI	6 mm	
	R/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
	L/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/10/2022	Inspection Date	01/11/2022	
	Survey held at	FONG MOTORS			
		1 KAKI BUKIT AVE 6			
		#01-27/01-45 SINGAPORE 417883			
5a.	Remarks				
	A)REGISTRATION DATE: 26 APR 2013 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 18 Working Days				