SA1B22AV0006 / AH LIM MOTOR COMPANY (BRANCH) ENTRY DATE & TIME: 31/10/2022 18:29 (SGT) SUBMITTED BY: GERALD CHEW VERSION: 1 (31/10/2022 18:29 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of materia facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the nsurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 31/10/2022 18:29 (SGT) Reported by Both Date of Accident 30/10/2022 19:00 (SGT) Exact Location of Accident Singapore Additional Location Information ANG MO KIO AVE 3 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDR3338P

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LAU JIAN SHEN NELSON NRIC No SXXXX675C **Email Address** PROPERTYATAS@GMAI .. COM Mobile Phone No (Phone) +65-97921567 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Toyota Model Wish Variant Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Auto CC

INSURANCE COMPANY

Name of Insurance Company Auto & General Insurance (Singapore) Pte. Limited. Policy Number / Cover Note Number P10434006R02

DRIVER

Name of Driver LAU JIAN SHEN NELSON NRIC No SXXXX675C Date Of Birth 01/12/1989 Occupation Indoor

Date Of Driving Pass 07/04/2009 Driving experience 13 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-97921567 Alt. Phone Number Email Address PROPERTYATAS@GMAIL.COM Address BLK 145 LORONG 2 TOA PAYOH #24-310 Address complement Postcode 310145 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Cross Junction Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 5 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name **QIANG BINGQING** Gender Female PASSENGER 2 LUCAS LAU Gender Male PASSENGER 3 Name LEA LAU Gender Female PASSENGER 4 Name SEVILLA RIO BORLAS Gender Female **DETAILS OF POLICE ACTION** Was the accident reported to the police? Yes Police Station Name Serangoon North Neighbourhood Police Post Police Station Address Blk 108 Serangoon North Avenue 1 #01-709 Singapore 550108 Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Yes Yes

ACCIDENT VIDEO IS WITH OWNER WORKSHOP

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG9155S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-1
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	= 0
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LAU JIAN SHEN NELSON
Gender	Male
Phone No	(Phone) +65-97921567
Address	_
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK AND ARM AREA
Injured person in which vehicle?	SDR3338P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No
INJURED 2	

injured percent in which vertice.	ODITOOOOI
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No
INJURED 2	
Name of injured person	QIAN BINGQING
Gender	Female
Phone No	(Phone) +65-90682234
Address	
Address Complement	-
Post Code	
Approximate Age Years Old	-
Injuries Sustained	NECK AND BACK AREA AREA
Injured person in which vehicle?	SDR3338P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No
INJURED 3	
Name of injured person	LUCAS LAU
Gender	Male
Phone No	-

Name of injured person	LUCAS LAU
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	
Injuries Sustained	HEAD AREA

Injured person in which vehicle? Were seat belts worn?	SDR3338P Yes
Was this injured conveyed to hospital by ambulance?	No
INJURED 4	
Name of injured person	LEA LAU
Gender	Female
Phone No	-
Address	
Address Complement	•
Post Code	
Approximate Age Years Old	
Injuries Sustained	UNKNOWN
Injured person in which vehicle?	SDR3338P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No
INJURED 5	
Name of injured person	SEVILLA RIO BORLAS
Gender	Female
Phone No	(Phone) +65-8916607
Address	•
Address Complement	
Post Code	
Approximate Age Years Old	
Injuries Sustained	THOM: THILL
Injured person in which vehicle?	SDR3338P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

Budget Direct Vehide: SDR 3338P

MPORTANT NOTICE

- I. Please report correctly the details of the accident to speed up the claims process.
- t. This Formmust be completed by the Pollcyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or within titing of material facts may Illow insurance companies to repudiate policy liability.
- 1. The Issue and acceptance of this Formby insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for Investigation.
- 3. The report will be forwarded by the insurers of the GIA Records Management Centre established by the Gent relinsurence Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application ty interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)


lunderstand, acknowledge, agree and consent that ;

- (a) My Insurer , my workshop and the General insurance Association of Singapore ("GIA") maylare permitted to collect, use, disclose (a) My Insurer, my workshop and the General insurance Association of Singapore ("GIA") maylare permised to collect use, osciose endire process my personal detailpersonal information is et out in inits (form) and any other personal information is evided by my or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' tawyers/law firms, the Monetary Authority of Singapon and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handing and/or dealing with my claims including the settlement of the claims and any necessary westigations relating to the claims;
- (ii) investigating the accident end/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (tr) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cay or of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may fare permitted to collect, use, disclose end/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their filled party service providers or agents (including their law yers flaw firms), which may be sited outside of Singapore, for one or more of the shove Purposes.

Sketch Plan



Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyhelder) / Date 8 Timo

Wittensed of Robbring Centre

ANKIALATOTOR COMPANY

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721 TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

LAU JIAN SHEN NELSON

c/o 46 Lentor Plain Singapore 786548 Not Northeries 1/Fmy & 22, 80ch Menny After Pains 14 day,

Date:

1/11/2022

QUANTITY		PARTICULARS			AMOUNT (\$)
	RE: TOYOTA WISH / SD	R 3338 P			
1 pc	front bonnet			,	R 896.00
2 pcs	front bonnet hinge @ 90	•	@	198.40	396.80
1 pc	front bonnet emblem logo			156.375A	79.00
1 pc	front bonnet heat shield	312-75		130.275	cm 352.00
8 pcs	front bonnet heat shield c	lip	@	3.20	25.60
1 pc	front bonnet rubber strip	86.50			W 276.50
1 pc	front bonnet lock	1.10			248.00
1 pc	front bonnet lock cable	171.60			263.10
1 pc	front bumper 565.8	6			<i>m</i> // 954.20
1 pc	front bumper reinforceme	nt 427.20			mry 564.80
1 pc	front bumper reinforceme	nt sponge 101,90			mry 274.40
2 pcs	front bumper side retaine		_	86.40	172.80
12 pcs	front bumper clip	. 0.0.0		2.70	m 32.40
2 pcs	front bumper fog lamp co	ver 6 \$ 2.30		253.20	mi) 506.40
2 pcs	front bumper fog lamp &	319-60 olsasi NIS BA	0	568.00	1,136.00
2 pcs	front head lamp assy	1344-16		2,583.70	Br 5,167.40
2 pcs	front head lamp lower bra	cket	@	135.00	270.00
1 pc	front bumper dust cover				CM 239.10
2 pcs	front bumper lower grille s		@	287.00	574.00
1 pc	front bumper centre air gr			K	483.40
1 pc	front bumper reinforceme			. 07	568.40
1 pc	front bumper reinforceme			1.4	400.30
1 pc	front grille chrome mouldi	ng			235.00
1 pc	windscreen washer tank	169.80			303.00
1 pc	front grille 391-60	LKK Auto Consultants hence notify		1,40	587.30
2 pcs	front grille clip	the Repairer of the following:	@	7.40	Mc 14.80
	Victor and	To resurvey before/after spray painting		ule katal	15 150 70
	G-g-	 To display damaged part(s) during resurvey Parts prices are subject to confirmation 		sub-total	15,150.70
		Third party survey is on a "Without Prejudice	e" basis		
		No illegal modification(s) is allowed			
	1.0	 Supplementary item(s) must be resurveyed is subject to final approval from Insurance C 			
		Acknowledged by Repairer			
		Signature:			
	t.	Date:			

	balance brought forwards.			15,150.70	
2 pcs 2 pcs 24 pcs 2 pcs 1 pc 1 pc 1 pc 1 pc	front fender Colling front fender dust cover front fender dust cover clip front fender housing panel front fender housing sub frame - outer front fender housing sub frame - inner front fender housing sub frame - upper section front fender housing sub frame - reinforcement brac front fender housing sub frame - reinforcement brac front head lamp panel front radiator lower panel front radiator top panel front radiator top panel front radiator brace panel radiator top panel trim garnish air con condenser	0000000	184.30 2.60 798.50	1,512.80 2,13 368.60 1,597.00 1,597.00 1,102.00 1,	しししてスーーーーして
1 pc 1 pc 2 pcs 1 pc	air con liquid pipe air con high pressure switch horn air con discharge hose		96.40	74 362.70 74 192.80 74 296.80	2+2
2 pcs 1 pc	air con condenser bracket radiator	@	26.30	Pri 52.60 7 Pri 859.40 7	2
1 pc	radiator top mount radiator top mount bracket radiator top hose radiator lower hose air con inlet pipe radiator fan cowling radiator fan motor radiator fan blade battery bracket air intake manifold auto transmission hose auto transmission gear selector auto transmission gear selector auto transmission oil sump	@	46.30 25.70	79.40 % 64.80 % 263.30 % 80 296.40 %	N X X X Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z

	balance brought forwards.			32,306.80
1	angina maunt bracket I / H			امر 132.00
1 pc	engine mount bracket L/ H			DN 153.70
pc	engine mount bracket R/H engine mount bracket front			Pil 185.30
pc			1099	P4 584.90
1 pc	front engine cross member lower cross member sub bracket	@	79.50	N 159.00
2 pcs	The second secon	<u>@</u>	70.00	n'i 452.40
1 pc	front lower arm			By 544.10
1 pc	front knuckle arm			Ma 265.40
1 pc	front wheel bearing 399.80			By 547.10
1 pc	front shock absorber 377.86 radiator top panel trim garnish clip	<u>@</u>	4.80	ne 28.80
6 pcs	radiator coolant expension tank	©	1.00	nd 244.70
1 pc	fuse/ relay junction box			CM 854.30
1 pc	engine air intake box cleaner			1m 34.00
1 pc	engine air intake box cleaner duct			nu 241.00
1 pc	engine air intake resonator chamber box 325.30			Da 495.40
1 pc	engine air intake box cleaner hose			_ nd 263.00
1 pc	ABS pump		In	215.00
1 pc	Windscreenwasher tank		,	Repeate 285.40
1 pc	Windscreenwasher tank motor			/m 268.00
1 pc				In 347.00
1 pc	front wiper panel trim	@	66.00	امر 132.00
2 pcs	front wiper panel corner cover front engine dust cover	<u>@</u>	00.00	cm 196.40
1 pc	front engine dust cover front engine dust cover clip	@	2.60	May 31.20
12 pcs	front dash board lower cover	<u>@</u>	2.00	Pez 367.20
1 pc	front dash board trim			In 1,994.20
1 pc	Iront dash board trim			1,001.20
			Sub-total	41,328.30
			Less 25%	10,332.08
			Sub-total	30,996.23
			Cub total	00,000.20
			0	
1 pc	battery	s.net	905a	180.00
1 pc	alloy rim	s.net		400.00
1 pc	tyre	s.net		Not 180.00 Not 400.00 Pm 260.00
4 liters	engine oil	s.net		125.00
7 liters	auto transmission oil	s.net		Me 140.00
1 bt	radiator coolant	s.net		38.00
	windscreen glass inner seal	s.net		na 45.00
1 pc	windscreen glass sealant	s.net		ne 45.00 ne 65.00
1 tube	EPR IU bracket	s.net		25.00
1 pc	LFIX 10 blacket	3.1101		20.00
			sub-total	32,274.23
			Jub total	02,214.20
	·			

Balance brought forwards.	32,274.23	
To remove and replace all the parts mentioned above, knock ng and straighten up the necessary affected areas.	2,600.00	001
To check wiring system.	100.00	301
To apply putty and spray painting on affected areas.	1,400.00	1300
To apply water proof sealant on affected areas.	300.00	2501
To apply rust proofing on affected areas.	300.00	<i></i>
To remove dash board to enable repair.	m 400.00	X
To remove carpet, trimming and seats to enable repair.	1 400.00	X
To replace air-con components and top up gas.	280.00	1001
To remove and install front undercarriage parts to enable repair.	260.00	1801
To replace alloy rim and perform wheel balancing.	40.00	201
To machine press wheel bearing.	80.00	201
To perform 4 wheels computerised alignment.	85.00	601
Towing charges.	70.00	501
To remove front windscreen glass to enable repair.	150.00	1201
To remove engine from engine bay to filicate repair.	800.00	3001
To benach mount , chassis alignment.	800.00	300! 250!
Total	40,339.23	

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721 TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

LAU JIAN SHEN NELSON

c/o 46 Lentor Plain Singapore 786548

Date 9/12/2022

QUANTITY		PARTICULARS	4 4	·	AMOUNT (\$)	1
QUANTITY	RE: TOYOTA WIAH / SDR		V	pa P	AMOUNT (\$)	
1 pc 1 pc 4 pcs 1 pc 1 pc	ABS pump A/C compressor brake line rear engine mount bracket air cleaner box assy			@ 325.00 4	2,165.00 7n 2,650.00 1,300.00 131.00 CM 657.40	- 840
1 pc 1 pc	battery tray undercariage front member			Papece.	7 165.90 1,095.00	-
				Sub-total less 25% sub-total	8,164.30 2,041.08 6,123.23	
				Total:	6,123.23	
					-	7
					=	_
						8201

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721 TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

LAU JIAN SHEN NELSON

c/o 46 Lentor Plain Singapore 786548

Date: 30/5/2023

QUANTITY	PARTICUI	LARS	AMOUNT (\$)	
	RE: TOYOTA WIAH / SDR 3338 P /SUPPLEMENTARY			
1 pc	alternator 1536.80	hous em	2,768.00	
		Sub-total less 25%	2,768.0 692.0	
		sub-total	2,076.0	
		Total:	2,076.0	
	,			

Veron Chen (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Wednesday, 7 June 2023 2:58 PM

To:

SUR

Subject:

FW: Request Finalisation for SDR 3338 P TOYO1 A WISH DOA 30102022

Attachments:

IMG_0147.jpg; IMG_1032.jpg; IMG_1033.jpg; IMG_1034.jpg; IMG_1198.jpg; IMG_ 1022.JPG; SDR 3338 P TOYOTA WISH DOA 30102022 SUPPLEMENTARY.pdf

Hi fyi.

CS/INC22010841/Kvy3

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claim.autoworxhouse@gmail.com <claim.autoworxhouse@gmail.com>

Sent: Wednesday, June 7, 2023 2:56 PM

To: Kenneth Kong (LKKAuto) < Kenneth Kong@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Request Finalisation for SDR 3338 P TOYOTA WISH DOA 30102022

Dear Kenneth,

We are requesting for the following items to finalise the matter.

- 1. Front engine cross member IMG 0147
- Windscreen washer tank & Windscreen washer tank motor -IMG 119 8/ IMG 1032 / IMG 1033 / IMG 1034
- 3. Front bumper lower grille side (Parts were missing at the time of the accident)
- 4. Alternator IMG 1022 (supplementary)

Besides can we request for increase the labour charge for 'To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.' To \$2,000.00 and fina ise at Lump Sum \$24,900.00.

Best regards,

Admin Team Autoworx House No.176 Sin Ming Drive

#02-01 Singapore 575721 Tel: 96725547 / 98634184

Fax: 64517423