



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22010866/Kvy3e2 Date: 12/05/2023 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YN 8868R
	Policy No.	Z22VC05012830	Coverage (\$)	0.00
	Claim No.	22/22/22/VC05/026384	Excess (\$)	700.00
	Assign From	GERALD POH	Assign Date	01/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi canter (M)	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	FEB71EA00165	Colour	WHITE
	Odometer	-	Steering	JAMMED
	Brakes	JAMMED	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/75 R17.5	AKINA	7 mm
	L/H Front Tyre	215/75 R17.5	AKINA	7 mm
	R/H Rear Tyre	215/75 R17.5 (D)	AKINA	6/6 mm
	L/H Rear Tyre	215/75 R17.5 (D)	AKINA	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/10/2022	Inspection Date	02/11/2022
	Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE MARKET VALUE IS S\$33,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days	