

H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Tel : 6484 4842 / Fax : 6484 4342

Email : info@hlcycle.com.sg

4 August 2021

Accident Date : 16 June 2021

Vehicle No : FBP 5085 P

Make / Model : Yamaha Sniper

Owner : Nur Haryani Binte Haron

Address : C/o: H L Cycle Pte Ltd
No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Description	Amount (SGD\$)
Lump Sum Repair as per recommendation	\$ 5,800.00
TOTAL	\$ 5,800.00