TP ondyet Direct Veron.

	FONG MOTO	ORS			
	1 Kaki Bukit Ave 6 #0				
	AutoBay@ Kaki Bukit, Sing				
	Tel: 6748 5648, Email: fongmo		om		
	Estimate of Cost of	f Repairs			
				29-Oct-2022	
				SKC9000U	
		Model BMW 5 E-Hybrid G30 CHASSIS/ENG# WBAJA92020G758770			
			CHASSIS/ENG#	WBAJA92020G758770	
	PARTS				
S/N	Item	Quantity	Unit Price	Amount	
1	M-Sport Front Bumper (PDC)	1	\$1,377.95	\$1,377.95	
2	M-Sport Front Bumper RH Outer L Frame	1	\$87.75	\$87.75	1
3	M-Sport RH LED Foglamp Crubel.	1	\$490.95	\$490.95 325.	_
4	M-Sport RH Foglight Cover Lat wen	1	\$94.80	\$94.80	
5	Headlamp Bracket Ne -	1	\$211.95	\$211.95	
6	Front Reinforcement Bar Zuf n	1	\$758.85	\$758.85	1
7	Front Reinforcement Sponge	1	\$76.50	\$76.50 *.	
8	PDC Sensor 1 Pille dund	6	\$254.05	\$1,524.30 254.05	
9	Adaptive LED Headlamp RH	1	\$4,960.60	\$4,960.60	
	Front Bumper RH Retainer	1	\$26.95	\$26.95	
11	PDC Holder WW	2	\$71.60	\$143.20 50	
12	RH Fender Review	1	\$992.05	\$992.05	7092.3
	M-Performance Front Splitter	1	\$4,323.04	\$4,323.04	
	Front RH Wheel Bearing	1	\$431.85	\$431.85	6737.6
14	Front Kir Wheel Bearing 7 v		Sub-total :	1 15,500.74	
	BMW F	Parts Discoun	5%	\$775.04	
			al After Discoun]
					_
CAL	NETT ITEMS	Quantity	Unit Price	Amount	+
S/N	M-Sport 19" Rim NL W	1	\$1.625.80	\$1,625.80	30.
2	Front Bumper Clip	1 Set	\$80.00	\$80.00 30	
	Tront Bumpo. Cup]
			Sub-total 2	\$1,705.80	-
	LABOUR				_
1	To replace and remove attachment on accident area		i i	\$1,000.00	0 -
2	Spray painting on all affected parts			\$1,000.00 250	800
3	For programming of headlamp and front bumper radar sensors			\$350.00 180	_
			Labour Tota	1 \$2,350.00	-
		Dort	s & Labour Tota	1 \$18 781 50	1
		Part	s & Labour Tota	\$18,781.50]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Adrin 7 1/5 16/11/22. 030mgs Colul: 7567.68 4/5: 6K.