



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010927/Awy3e2 Date: 30/01/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1476P	Veh. Inspected	SJL 2683J
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/10/22/7025	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	02/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	GE61108481	Colour	BLUE
	Odometer	263163 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/10/2022	Inspection Date	02/11/2022
	Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	