



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428		Ref: CS/LIP22010935/Rny3m4 Date: 30/01/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 7405J	Veh. Inspected	SND 4002G
Policy No.		Coverage (\$)	0.00
Claim No.	AVS22/3049	Excess (\$)	0.00
Assign From	TED SEAH	Assign Date	01/11/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS PLUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JTDZS3EU70J067915	Colour	GREY
Odometer	45261 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60R16	WEST LAKE	6 mm
L/H Front Tyre	205/60R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60R16	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/10/2022	Inspection Date	02/11/2022
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks			
A)REGISTRATION DATE: 28 DEC 2021 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	