



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
YEO PERUMAL MOHIDEEN LAW CORPORATION 1 COLEMAN STREET #05-10 THE ADELPHISINGAPORE 179803 ON BEHALF OF TAN JUN YOU			Ref: CS/LAW22010946/Ewy3e2 Date: 07/12/2022 Code: L109	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	FBD 7274K	
	Policy No.	Coverage (\$)	0.00	
	Claim No. PA.9092-22/FC	Excess (\$)	0.00	
	Assign From	Assign Date	02/11/2022	
2. Vehicle Particulars & Condition				
	Make & Model	HONDA WAVE	c.c	125
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	NF125ST0027710	Colour	BLUE
	Odometer	16417 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	PIRELLI	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90-17	PIRELLI	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/09/2022	Inspection Date	03/11/2022
	Survey held at	34 TOH GUAN ROAD EAST #01-24 S 608579		
	Repairer	ONE 78 PERFORMANCE		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	