



Your Ref : 1202200044463

Date: 25<sup>th</sup> Nov 2022

Our Ref : CS4/FWD22010948/Uqy3m4

**M/s FWD Singapore Pte Ltd**  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBB 7707P  
ACCIDENT ON 21/10/2022**

Instruction was received to inspect the vehicle Reg. No. FBB 7707P. The inspection was conducted on 03/11/2022 at the premises of M/s Ban Hock Hin Co Pte Ltd, No. 6 Defu Lane 4, Singapore 539410.

The following vehicle information was recorded:

Registration Number : FBB 7707P  
Make/Model : Yamaha YZF-R6S  
Year of Registration : 2007  
Body Colour : White  
Chassis Number : JYARJ111000023628  
Engine Capacity : 599 cc

The motorcycle caught fire. The cause of fire probably due to electrical short circuit. The Estimated repair cost of such vehicle is S\$8,526.25 (Sin Dollars: Eight Thousand Five Hundred and Twenty Six and Cents Twenty Five only.) (Exclude check items S\$2,544.60Nett) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **“uneconomical Total Loss”**.

(a) If the vehicle to be “Total Loss”

Market Value	S\$ 10,000.00 (est)
<i>Less: LTA Reimbursement Value (RV)</i>	<i>(S\$ 2,758.00)</i>
	<hr/>
Nett Liability	S\$ 7,242.00

S\$ 7,242.00

(b) If the vehicle to be “Repair”

Repair Cost (Est) (Exclude check items S\$2,544.60Nett)	S\$ 8,526.25
	<hr/>

Nett Liability

S\$ 8,526.25

(a) – (b) =

(S\$ 1,284.25)

=====

The amount of estimated saving of S\$1,284.25 if the vehicle to be written off as **“Total Loss”** instead of to be repair.

Vehicle Inspected By:



CHUA KANG SENG  
*Licensed Appraiser*



K.K.LAU  
*MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust),MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),  
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.