

ASS. REC. BY: P. Paul

REF:

CS/FC122010949/Rg3

426C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL 5486Tat Workshop m/s WEARNESof 249, Alexander RdInsured: FC12

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 68K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL 5486T Yr Regn: 2017 / FEBType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: VOLVO V40 12(A) C.C. 1498Colour GOLD A/C: Insured / Std / NI / NASp. Reading 53549 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 4V1MV2840H2412508Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16R: 21BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mmRear R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 26/10/22 D.O.I. 15/02/23Survey held at WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 34K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS. SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.B.L. (%)

SERVICE ESTIMATE

88817 - C00001 SL: SERVICE SALES - PC

Mr Yu Qi
BLK 245 Simei Street 5
#04-60

Singapore 520245

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Yu Qi

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1
Inv.date. : 27/10/2022
WIP No. . : 47471
Veh.In/Out:
*Tel.No. . : Mobile: 93398579
Reg.No. . : SLL5486T
Reg.date . : 28/02/2017
Mileage .. : 0
Chassis No: YV1MV28H0H2412508

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE RHR DOOR, RHR FENDER, REAR BUMPER, BRACKETS, CLIPS, ETC. <i>850X4.5</i>	0	5950.00	0		5,950.00	S <i>3825</i>
800	TO BLEND AND SPRAY PAINT ON RHR DOOR, RHR FENDER, RHS FENDER INNER PANEL, RHS ROOF TOP SIDE / PANEL, REAR BUMPER, ETC. <i>750X4</i>	0	3750.00	0		3,750.00	S <i>3000</i>
802	TO REPLACE RHR QTR GLASS <i>phh</i>	0	850.00	0		850.00	S ✓
89994	TO INSTALL RHR QTR GLASS	0	280.00	0		280.00	S ✓
SOLAR FILM							
802	TO REMOVE AND INSTALL INTERIOR PARTS	0	2550.00	0		2,550.00	S <i>1700</i>
802	TO REMOVE AND INSTALL REAR BOO COMPARTMENT PARTS	0	1700.00	0		1,700.00	S <i>850</i>
802	TO REMOVE AND INSTALL PETROL TANK	0	1700.00	0		1,700.00	S <i>850</i>
0031	TO REPLACE RHR RIM	0	50.00	0		50.00	S ✓

SERVICE ESTIMATE

88817 - C00001 SL: SERVICE SALES - PC

Mr Yu Qi
BLK 245 Simei Street 5
#04-60

Singapore 520245

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Yu Qi

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2
Inv.date. : 27/10/2022
WIP No. . : 47471
Veh.In/Out:
*Tel.No. . : Mobile: 93398579
Reg.No. . : SLL5486T
Reg.date . : 28/02/2017
Mileage ... : 0
Chassis No: YV1MV28H0H2412508

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
10	WHEEL ALIGNMENT	0	280.00	0		280.00	S ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0		588.00	S ✓
	ALLOY RIM 16 "Markeb	1.0 EA	749.10	10		674.19	S
	BUMPER COVER REAR V4 <i>sea</i>	1.0 EA	1865.70	10		1,679.13	S
	BUMPER BRACKET REAR ?	1.0 EA	182.10	10		163.89	S
	FENDER REAR RH V40/C <i>bt</i>	1.0 EA	1723.40	10		1,551.06	S
	NOISE DEADENING PAD <i>a</i>	3.0 EA	606.90	10		1,638.63	S
	SEAM SEALANT <i>m</i>	1.0 EA	49.00	10		44.10	S
	REAR DOOR PANEL RH V <i>regan</i>	1.0 EA	2373.50	10		2,136.15	S
	QTR GLASS BLACK RH V <i>m/plu</i>	1.0 EA	560.60	10		504.54	S
	D REPAIR SEALANT G <i>de</i>	1.0 EA	761.80	10		685.62	S
	2-PART FLEXIBLE FOAM <i>m</i>	1.0 EA	210.00	10		189.00	S
	PLASTIC ADHESIVE WUR <i>m</i>	1.0 EA	70.00	10		63.00	S
	D PRIMER GLASS & P <i>m</i>	1.0 EA	45.50	10		40.95	S
	D GLASS CLEANER H <i>m</i>	1.0 EA	86.60	10		77.94	S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

88817 - C00001 SL: SERVICE SALES - PC

Mr Yu Qi
BLK 245 Simei Street 5
#04-60

Singapore 520245

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Yu Qi

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 27/10/2022

WIP No. . : 47471

Veh.In/Out:

*Tel.No. . : Mobile: 93398579

Reg.No. . : SLL5486T

Reg.date . : 28/02/2017

Mileage .. : 0

Chassis No: YV1MV28HOH2412508

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	D WINDSCREEN SEALA <i>m</i> ✓	2.0 EA	172.70	10		310.86	S
	BUMPER INSTALLING MT <i>m</i> ✓	1.0 EA	101.40	10		91.26	S
	BUMPER CLIP XC90 16- <i>m</i> ✓	10.0 EA	8.80	10		79.20	S
	BLIND RIVET 4.0*21 P <i>m</i> ✓	10.0 EA	5.00	10		45.00	S
	BUMPER CLIP 8x8,5 <i>m</i> ✓	10.0 EA	8.20	10		73.80	S
	BUMPER CLIP GREEN S6 <i>m</i> ✓	10.0 EA	6.00	10		54.00	S
	EXPANDING NUT XC40 1 <i>m</i> ✓	10.0 EA	6.70	10		60.30	S

Rasul
Hp 90010068
12 days
15/02/23 @1420
Resu before put

Labour Total 17,698.00
Parts Total 10,162.62
Package Total 0.00

Gross Total. 27,860.62
Net..... 27,860.62
GST @ 7.0% 1,950.24
Total..... 29,810.85
Paid..... 0.00
Please Pay.. 29,810.85

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 426C

Vehicle Details

Vehicle No.: SLL5486T

Vehicle to be Exported: No

Intended Deregistration Date: 19 Feb 2023

Vehicle Make: VOLVO

Vehicle Model: V40 T2 (A)

Primary Colour: Gold

Manufacturing Year: 2016

Engine No.: B4154T51901433

Chassis No.: YV1MV28H0H2412508

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$23,513.00

Original Registration Date: 28 Feb 2017

First Registration Date: 28 Feb 2017

Transfer Count: 0

Actual ARF Paid: \$19,919.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Feb 2027

PARF Rebate Amount: \$13,943.00

Intended COE Rebate Details

COE Expiry Date: 27 Feb 2027

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$48,556.00

COE Rebate Amount: \$19,475.00

Total Rebate Amount: \$33,418.00

Volvo V40 T2

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$68,822****Depreciation** ⓘ

\$14,640 /yr

[View models with similar depre](#)**Reg Date**

27-Feb-2017

(4yrs 7days COE left)

Mileage

56,568 km (9.5k /yr)

Manufactured ⓘ

2016

Road Tax ⓘ

\$684 /yr

Transmission

Auto

Dereg Value ⓘ\$33,824 as of today ([change](#))**OMV** ⓘ

\$23,513

COE ⓘ

\$49,430

ARF ⓘ

\$19,919

Engine Cap

1,498 cc

Power

90.0 kW (120 bhp)

Curb Weight ⓘ

1,454 kg

No. of Owners ⓘ

2

Type of Vehicle[Hatchback](#)