



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:TEE LEE GREEN		Ref: CC4/ASM22010960/Rpa3q2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHF 748A	Veh. Inspected	SG 3024A
Policy No.	P2459880	Coverage (\$)	0.00
Claim No.	S2M04DJR	Excess (\$)	0.00
Assign From		Assign Date	01/11/2022
2. Vehicle Particulars & Condition			
Make & Model	VOLVO B5LH AUTO	c.c	5132
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	YV3T1U222JA192390	Colour	GREEN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	MICHELIN	8 mm
L/H Front Tyre	275/70 R22.5	MICHELIN	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/10/2022	Inspection Date	01/11/2022
Survey held at	310 MANDAI RD		
Repairer	TOWER TRANSIT SINGAPORE PTE. LTD.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	