



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22010965/Kvy3e2 Date: 19/05/2023 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SMP 1550J
	Policy No.	Z22VP05031931	Coverage (\$)	0.00
	Claim No.	22/22/22/VP05/024677	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	02/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI I30 1.4 T (A)	c.c	1353
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	TMAH3513VKJ113964	Colour	RED
	Odometer	24079 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	8 mm
	L/H Front Tyre	205/55 R16	MICHELIN	8 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	8 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2022	Inspection Date	02/11/2022
	Survey held at	CHENG HOE MOTOR SERVICE 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047		
5a. Remarks				
	A)THE MARKET VALUE IS S\$100,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	