

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : D22003399MFCV Date: 28th Nov 2022

Our Ref : CS/FCI22010966/Kqy3m4

M/s MS First Capital Insurance Ltd

16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBC 2735K INSURED VEHICLE: YQ 1114M ACCIDENT ON 28/10/2022

Instruction was received to inspect the vehicle Reg. No. GBC 2735K. The inspection was conducted on 16/11/2022 at the premises of M/s Cheng Hoe Motor Pte Ltd, Blk 1019 Yishun Ind Park A #01-374/382, Singapore 768761.

The following vehicle information was recorded:

Registration Number : GBC 2735K

Make/Model : Nissan Cabstar 3.0 5M/T Abs 2DR 2WD Turbo

Year of Registration : 2011 Body Colour : White

Chassis Number : JN1SC2F24Z0850191

Engine Capacity : 2953 cc

The vehicle sustained damages at the rear portion. The Estimated repair cost of such vehicle is \$\$41,341.29 (Sin Dollars: Forty One Thousand Three Hundred and Forty-One and Cents Twenty Nine only.) (Exclude check items \$\$2,466.84Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "uneconomical Total Loss".

(a) If the veh Market V	icle to be "Total Loss" alue	S\$	35,000.00 (es	st)	
Less: LTA	Reimbursement Value (RV)	(S\$	15,873.00)		
Nett Liabi	lity	S\$	19,127.00		
(b) <u>If the vehic</u>	cle to be "Repair"		S	\$	19,127.00
Repair Cost	(Est)	S\$	41,341.29		

Nett Liability

(Exclude check items \$\$2,466.84Nett)

S\$ 41,341.29

(a) - (b) = (S\$ 22,214.29)

The amount of estimated saving of S\$22,214.29 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG Licensed Appraiser

K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.