

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22010971/y3	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 17705		Date:	03/11/2022	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 5820L	Veh. Inspected	ł	FBT 3185B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/10/22/2092	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		02/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	- Steering				
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
_						
5.	General Information					
	Accident Date	29/10/2022	Inspection Dat	e	07/11/2022	
	Survey held at	ENG SOON PAINTING SVC				
		BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					