

ASS. REC. BY:

Steve

CS/CT122P1102.7/Eqp3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X
X	X
X	X

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GRL 10952 Yr Regn: 26/3/21
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Renault Kangoo c.c. Electric Car
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 33200 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YKIF WEZHN6530 95.80
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or: Continental
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 28/10/21 D.O.I. 4/11/22
 Survey held at Wiggins
 Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-93K</u>
	<u>PR-33,714</u>
	<u>NR-59,786</u>

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.S.: (£ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + P.S. \$ _____

Photos

Others

TOTAL

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

GST Reg.No:M28920628X

Singapore 159103

Inv.No. : B&P 0 Page 1
 Inv.date : 04/11/2022
 WIP No. : 47842
 Veh.In/Out: 31/10/2022
 *Tel.No. : -
 Reg.No. : GBL1495L
 Reg.date : 26/03/2021
 Mileage : 0
 Chassis No: VF1FEWZHN65302580

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE LHS SLIDING DOOR, LHR FENDER, LHR DOOR, RHR DOOR, RHR FENDER, RHS SLIDING DOOR, REAR BUMPER, REINFORCEMENT, TAILLAMPS, DEFLECTORS, EMBLEMS, WIPER ARMS, BRACKETS, CLIPS, ETC (not include fhr p1)	0	8250.00	0		8,250.00 S	7700
800	TO BLEND AND SPRAY PAINT ON LHS SLIDING DOOR, LHR FENDER, LHS FENDER INNER PANEL, LHS ROOF TOP SIDE PANEL, LHR DOOR, RHR DOOR, RHR FENDER, RHS FENDER INNER PANEL, RHS ROOF RHS SLIDING DOOR, ETC.	0	7150.00	0		7,150.00 S	6500
802	TO TRANSFER DOOR PARTS	0	1000.00	0		1,000.00 S	500
802	TO REPLACE LHS SLIDING DOOR GL LHR FENDER GLASS, LHR DOOR GLASS, RHR DOOR GLASS, RHR FENDER GLASS, RHS SLIDING DOOR GLASS, ETC.	0	3300.00	0		3,300.00 S	1650

Steve CLKK)
 4/11/22, 5pm
 m R
 30 dys
 PIP
 by R y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
45 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 04/11/2022

WIP No. . : 47842

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Reg.date . : 26/03/2021

Mileage . : 0

Chassis No: VF1FWEZHN65302580

Singapore 159103

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
0080	TO INSTALL LHS SLIDING DOOR	0	280.00	0		280.00 S	X
	GLASS SOLAR FILM						
0080	TO INSTALL LHR FENDER DOOR	0	280.00	0		280.00 S	/
	GLASS SOLAR FILM						
0080	TO INSTALL LHR DOOR GLASS	0	280.00	0		280.00 S	/
	SOLAR FILM						
0080	TO INSTALL RHR DOOR GLASS	0	280.00	0		280.00 S	/
	SOLAR FILM						
0080	TO INSTALL RHR FENDER GLASS	0	280.00	0		280.00 S	X
	SOLAR FILM						
0080	TO INSTALL RHS SLIDING DOOR GL	0	280.00	0		280.00 S	X
	SOLAR FILM						
802	TO REMOVE AND INSTALL INTERIOR	0	1650.00	0		1,650.00 S	1100
	PARTS						
802	TO REMOVE AND INSTALL REAR BOO	0	1100.00	0		1,100.00 S	550
	COMPARTMENT PARTS						
802	TO REMOVE AND INSTALL PETROL	0	1650.00	0		1,650.00 S	?

550 x 2

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
45 Leng Kee Road

Singapore 159103

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Wearnes Automotive P

GST Reg.No: M28920628X
0 Page 3
Inv.No. . : B&P
Inv.date. : 04/11/2022
WIP No. . : 47842
Veh.In/Out: 31/10/2022
*Tel.No. . : -
Reg.No. . : GBL1495L
Reg.date ..: 26/03/2021
Mileage ... : 0
Chassis No: VF1FWEZHN65302580

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
TANK							
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00	S ✓
	RESETTING OF ALL ELECTRICAL						
	MODULES						
R16	TOWING CHARGES	0	250.00	0		250.00	S ✓
	(ACCIDENT SCENE TO RENAULT)						
802	TO REPLACE FRONT BUMPER, BUMPE	0	1100.00	0		1,100.00	S 550
	GARNISH, RHS FOG LAMP, ETC						
R06	TO REPLACE FRONT AND REAR	60 X 2	120.00	0		120.00	S ✓
	NUMBER PLATE W HOLDER						
	BODY ASSY SIDE-RR LH ✓ 00	1.0 EA	1818.90			1,818.90	S
	REINF-LH CTR RAIL ?	1.0 EA	275.10			275.10	S
	FUEL FILLER BRACKET ?	1.0 EA	198.30			198.30	S
	AIR DUCT PANEL LH ✓ OR	1.0 EA	77.00			77.00	S
	REINF ASSY-LH RR DOO ✓ REC	1.0 EA	15.80			15.80	S
	BOX ASSY-LH SLIDE DO ?	1.0 EA	233.20			233.20	S
	FENDER INNER PANEL L ✓ 00	1.0 EA	3108.60			3,108.60	S

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 T 6430 4700 www.wearnes.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
45 Leng Kee Road

GST Reg.No:M28920628X

Singapore 159103

Inv.No. . : B&P 0 Page 4

Inv.date. : 04/11/2022

WIP No. . : 47842

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Reg.date . : 26/03/2021

Mileage . : 0

Chassis No: VF1FWEZHN65302580

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TAILLAMP PANEL INNER / 00	1.0 EA	604.60			604.60	S
	PLR ASSY-END RR LH / 00	1.0 EA	1008.90			1,008.90	S
	PLR-RR END LH, UPR P / 00	1.0 EA	897.70			897.70	S
	BUMPER REINFORCEMENT / 00	1.0 EA	547.20			547.20	S
	WHEEL HOUSING REAR L / 00	1.0 EA	773.60			773.60	S
	BRKT-2ND ROW LH SEAT ?	1.0 EA	234.70			234.70	S
	ANCH ASSY-BENCH, SIDE ?	1.0 EA	133.90			133.90	S
	APRON-RR / 00	1.0 EA	866.30			866.30	S
	CRSSMMBR-END / 00	1.0 EA	545.30			545.30	S
	BRKT ASSY-UREA ADDIT ?	1.0 EA	176.10			176.10	S
	FLOOR-RR PART,RR / 00	1.0 EA	996.80			996.80	S
	FUEL FLAP COVER / BR	1.0 EA	83.30			83.30	S
	DIESEL FLAP HOLDER / BR	1.0 EA	275.70			275.70	S
	CLIP - RETAINING / MC	1.0 EA	2.80			2.80	S
	LOCK-FUEL FLAP ?	1.0 EA	146.00			146.00	S
	CABLE-FUEL FLAP DISC ?	1.0 EA	102.10			102.10	S
	FUEL FLAP LOCK K2 ?	1.0 EA	254.90			254.90	S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)

Inv.No. . : GST Reg.No: M28920628X
B&P Page 5

Inv.date. : 04/11/2022

WIP No. . : 47842

Singapore 159103

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Closed by : Michelle Ong Siew Be

Reg.date .: 26/03/2021

Svc Consultant :

Mileage ... : 0

Remarks : Wearnes Automotive P

Chassis No: VF1FWEZHN65302580

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COVER-MTG, ENERGY FL ?	1.0 EA	72.40			72.40	S
	SPOILER-RR ?	1.0 EA	519.40			519.40	S
	DEFLECTOR REAR RH K2 X	1.0 EA	149.70			149.70	S
	DEFLECTOR REAR LH K2 / BR	1.0 EA	142.80			142.80	S
	BUMPER REAR K2 / BR	1.0 EA	675.70			675.70	S
	PROTECTOR ?	1.0 EA	542.60			542.60	S
	REVERSE SENSOR HOLDE / MK	1.0 EA	55.20			55.20	S
	BUMPER BRACKET REAR / BR	1.0 EA	299.40			299.40	S
	BUMPER BRACKET REAR / BR	1.0 EA	173.40			173.40	S
	DOOR TRIM FRT LH K2 X	1.0 EA	223.30			223.30	S
	DOOR TRIM REAR LH X BR	1.0 EA	209.50			209.50	S
	FENDER MLDG REAR LH / CUT	1.0 EA	266.40			266.40	S
	LOGO 'KANGOO' REAR K / MK	1.0 EA	181.10			181.10	S
	EMBLEM " RENAULT " R / MK	1.0 EA	189.80			189.80	S
	SUPT-LICENCE PLATE / CUT	1.0 EA	216.40			216.40	S
	SHIELD-WH, RR LH / BR	1.0 EA	239.90			239.90	S
	SHIELD-RR RH WHEE X	1.0 EA	250.30			250.30	S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
45 Leng Kee Road

GST Reg.No:M28920628X

Singapore 159103

Inv.No. . : B&P 0 Page 6
Inv.date. : 04/11/2022
WIP No. . : 47842
Veh.In/Out: 31/10/2022

*Tel.No. . : -
Reg.No. . : GBL1495L
Reg.date . : 26/03/2021
Mileage . : 0
Chassis No: VF1FWEZHN65302580

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount G
	BUMPER AIR DUCT VENT <i>OR</i>	2.0 EA	73.50	147.00 S
	DOOR REAR LH K2 <i>DD</i>	1.0 EA	2089.40	2,089.40 S
	DOOR REAR RH K2 <i>DD</i>	1.0 EA	2089.40	2,089.40 S
	BOOT CHECK HINGE K2 : <i>??</i>	2.0 EA	115.30	230.60 S
	BOOT CHECK HINGE K2	2.0 EA	143.40	286.80 S
	DOOR STOP FWOA ?	2.0 EA	115.30	230.60 S
	BOOT HINGE UPPER K2 <i>BT</i>	2.0 EA	282.30	564.60 S
	BOOT HINGE LOWER K2 <i>BT</i>	2.0 EA	282.30	564.60 S
	STOP <i>PC</i>	2.0 EA	4.70	9.40 S
	RAIL-RH SLIDE DOOR, <i>X</i>	1.0 EA	500.90	500.90 S
	RAIL-SIDE RH SLIDE D <i>X</i>	1.0 EA	500.90	500.90 S
	RAIL-SIDE RH SLIDE D <i>X</i>	1.0 EA	478.30	478.30 S
	ROLLER TOP RH <i>X</i>	1.0 EA	144.10	144.10 S
	ROLLER COMPL - SLDG <i>X</i>	1.0 EA	29.80	29.80 S
	RUNNER-SIDE SLIDE DO <i>X</i>	1.0 EA	241.00	241.00 S
	HINGE PIN <i>X</i>	1.0 EA	95.90	95.90 S
	YOKE-SIDE SLIDE DOOR <i>X</i>	1.0 EA	73.30	73.30 S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 7

Inv.date. : 04/11/2022

WIP No. . : 47842

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Reg.date . : 26/03/2021

Mileage ... : 0

Chassis No: VF1FWEZHN65302580

Singapore 159103

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SLIDING ROLLER LOWER X	1.0 EA	340.80			340.80	S
	DOOR STOP X	1.0 EA	144.30			144.30	S
	RAIL-SIDE LH SLIDE D / BT	1.0 EA	500.90			500.90	S
	SLIDING DOOR RAIL CT / BT	1.0 EA	478.30			478.30	S
	RAIL-LH SLIDE DOOR, ?	1.0 EA	500.90			500.90	S
	BRKT-SIDE SLIDE DOOR ?	1.0 EA	144.30			144.30	S
	ROLLER COMPL - SLDG ?	1.0 EA	29.80			29.80	S
	SLIDING DOOR CTR ROL ?	1.0 EA	241.00			241.00	S
	HINGE PIN ?	1.0 EA	95.90			95.90	S
	YOKE-SIDE SLIDE DOOR ?	1.0 EA	73.30			73.30	S
	SLIDING DOOR LOWER R ?	1.0 EA	340.80			340.80	S
	REINF-LH SIDE SLIDE ?	1.0 EA	171.60			171.60	S
	DOOR STOP ?	1.0 EA	144.30			144.30	S
	SUPT-RH SIDE SLIDE D ?	1.0 EA	171.50			171.50	S
	BODY ASSY SIDE-RR RH X R	1.0 EA	1616.30			1,616.30	S
	REINF-RH CTR RAIL ?	1.0 EA	275.10			275.10	S
	MBR-CLOSING-RR RH EN ?	1.0 EA	147.30			147.30	S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
45 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 8

Inv.date. : 04/11/2022

WIP No. . : 47842

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Reg.date . : 26/03/2021

Mileage ... : 0

Chassis No: VF1FWEZHN65302580

Singapore 159103

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount G
	ROOF X R	1.0 EA	2232.70	2,232.70 S
	LOCK BARREL ?	1.0 EA	315.00	315.00 S
	DOOR STOP UPPER ?	1.0 EA	14.50	14.50 S
	BOOT BUFFER K2 ?	1.0 EA	57.70	57.70 S
	BOOT BUFFER CATCH K2 ?	1.0 EA	38.10	38.10 S
	DOOR HANDLE OUTER K2 X	1.0 EA	152.30	152.30 S
	DR OUTER HANDLE COVE X	1.0 EA	21.70	21.70 S
	HANDLE MODULE RH FWO ?	1.0 EA	173.30	173.30 S
	CONT-LH DOOR OPEN, IN ?	1.0 EA	126.60	126.60 S
	BOOT CATCH K2 ?	1.0 EA	378.40	378.40 S
	BUTEE SUP P ?	1.0 EA	7.40	7.40 S
	BOOT LOCK TOP K2 ?	1.0 EA	242.90	242.90 S
	BOOT LOCK LOWER K2 ?	1.0 EA	242.90	242.90 S
	LOCK-SUPER LOCK, LH ?	1.0 EA	483.30	483.30 S
	RIVET ?	10.0 EA	9.10	91.00 S
	HANDLE LOCK NUT K2 ?	4.0 EA	13.60	54.40 S
	LINK LOCK ?	1.0 EA	18.70	18.70 S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 9

Inv.date. : 04/11/2022

WIP No. . : 47842

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Reg.date .: 26/03/2021

Mileage ... : 0

Chassis No: VF1FWEZHN65302580

Singapore 159103

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount G
	OUTER HANDLE SUPPORT ?	1.0 EA	29.50	29.50 S
	SLIDING DOOR LH K2 ?	1.0 EA	2232.90	2,232.90 S
	SLIDING DOOR RH K2 X	1.0 EA	2232.90	2,232.90 S
	MISC OTR ACCESS ?	1.0 EA	518.10	518.10 S
	MISC OTR ACCESS ?	1.0 EA	518.10	518.10 S
	SLIDING DOOR LOCK ME ?	1.0 EA	418.00	418.00 S
	SLIDING DOOR LOCK ME ?	1.0 EA	424.20	424.20 S
	BOOT SEAL K2 / CRU	1.0 EA	245.40	245.40 S
	BODY SEAL / CRU	1.0 EA	358.10	358.10 S
	BOOT SEAL CTR K2 / CRU	1.0 EA	221.80	221.80 S
	DOOR RUBBER STRIP RE / CRU	1.0 EA	103.30	103.30 S
	NOISE DEADENING PAD / PR	3 8.0 EA	606.90	3,641.40 S
	PRIMER / PR	3 8.0 EA	204.70	1,228.20 S
	WINDSCREEN SEALANT / PR	3 12.0 EA	134.00	1,608.00 S
	3RD ROW GLASS RH K2 PR	1.0 EA	655.60	655.60 S
	3RD ROW GLASS LH K2 PR	1.0 EA	655.60	655.60 S
	SL/ GLASS RH K2 SWB X	1.0 EA	312.40	312.40 S

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T 6430 4700 www.wearnes.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
45 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 10

Inv.date. : 04/11/2022

WIP No. . : 47842

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Reg.date .: 26/03/2021

Mileage ... : 0

Chassis No: VF1FWEZHN65302580

Singapore 159103

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SL/ GLASS LH K2 SWB X	1.0 EA	312.40			312.40	S
	WINDSCREEN REAR LH K	1.0 EA	535.20			535.20	S
	WINDSCREEN REAR RH K	1.0 EA	535.20			535.20	S
	KIT-SEAL, WDW GLASS	1.0 EA	403.30			403.30	S
	KIT-SEAL, WDW GLASS	1.0 EA	410.20			410.20	S
	SEAL-SIDE WDW FINISH	1.0 EA	180.30			180.30	S
	SEAL-SIDE WDW FINISH	1.0 EA	175.50			175.50	S
	WSTRIP-TRUNK DOOR WD	1.0 EA	371.50			371.50	S
	BODY SEAL	1.0 EA	811.30			811.30	S
	TAILAMP-RR LH K2	1.0 EA	161.60			161.60	S
	TAILAMP,RR RH K2 X	1.0 EA	161.60			161.60	S
	MOULDING BODY LH	1.0 EA	86.00			86.00	S
	MOULDING BODY RH X	1.0 EA	86.00			86.00	S
	REFLECTOR LAMP LH K2	1.0 EA	100.00			100.00	S
	REFLECTOR LAMP RH K2 X	1.0 EA	117.60			117.60	S
	THRID BRAKE LAMP K2 X	1.0 EA	129.30			129.30	S
	NUMBER PLATE LAMP K2 ?	1.0 EA	142.60			142.60	S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

GST Reg.No:M28920628X

Singapore 159103

Inv.No. . : B&P 0 Page 11
 Inv.date. : 04/11/2022
 WIP No. . : 47842
 Veh.In/Out: 31/10/2022
 *Tel.No. . : -
 Reg.No. . : GBL1495L
 Reg.date .: 26/03/2021
 Mileage ... : 0
 Chassis No: VF1FWEZHN65302580

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price Disc%	Pkg	Amount G
	NUMBER PLATE LAMP KJ ?	2.0 EA	35.10		70.20 S
	REAR WIPER MOTOR ?	1.0 EA	507.10		507.10 S
	WASHERS / PK	1.0 EA	15.30		15.30 S
	RIVET HEAT SHIELD S2 / PK	10.0 EA	10.10		101.00 S
	WIPER ARM REAR / GT	1.0 EA	83.00		83.00 S
	WIPER BLADE REAR K2 / CVT	1.0 EA	33.90		33.90 S
	WIPER NOZZLE REAR K2 / MIS	1.0 EA	42.60		42.60 S
	RR SCRWN WSH PIP / PK	1.0 EA	91.30		91.30 S
	JOINT-ELBOW / PK	1.0 EA	27.00		27.00 S
	TUBE-BACKLITE WASH / PK	1.0 EA	48.00		48.00 S
	TRUNK TRIM REAR LHS / BR	1.0 EA	547.20		547.20 S
	TRIM -TRUNK, UPR RR ? / BR	1.0 EA	129.30		129.30 S
	PARK AID SENSOR BOTH / BR (CTR)	2.0 EA	369.40		738.80 S
	PARK SENSOR RR BOTH / BR	2.0 EA	369.40		738.80 S
	SPCR-MTG,RR CAMERA ?	1.0 EA	28.30		28.30 S
	CLIP-MTG,RR CAMERA ?	1.0 EA	29.50		29.50 S
	CAMERA-RR ?	1.0 EA	1191.00		1,191.00 S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 12

Inv.date. : 04/11/2022

WIP No. . : 47842

Veh.In/Out: 31/10/2022

*Tel.No. . : -

Reg.No. . : GBL1495L

Reg.date .: 26/03/2021

Mileage ..: 0

Chassis No: VF1FWEZHN65302580

Singapore 159103

Closed by : Michelle Ong Siew Be
 Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SEAM SEALANT / <i>AK</i>	6.0 EA	49.00			294.00	S
	REVERSE SENSOR HARNE <i>TH</i>	1.0 EA	529.10			529.10	S
	BUMPER FRT COVER <i>CRN</i>	1.0 EA	509.70			509.70	S
	BUMPER FRT FWOZ <i>AK</i>	1.0 EA	932.80			932.80	S
	FOG LAMP LH/RH GS3/ <i>?</i>	2.0 EA	119.80			239.60	S

Gross Total. 90,878.60

Labour Total 27,700.00
 Parts Total 63,178.60
 Package Total 0.00

Net..... 90,878.60

GST @ 7.0% 6,361.50

Total..... 97,240.10

Paid..... 0.00

Please Pay.. 97,240.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

4842
China Tanyang
- TP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/10/2022 11:11 (SGT)
Reported by	Driver
Date of Accident	28/10/2022 10:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TOWARDS TUAS AFTER TOH GUAN EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBL1495L

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	WEARNES AUTOMOTIVE PTE LTD
Company Reg No	1XXXXX400R
Email Address	tecklam@urban-renewables.com
Mobile Phone No	(Phone) +65-96347475
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Renault
Model	Kangoo
Variant	KANGOO EV
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	0

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD22V01029

DRIVER

Name of Driver	TEO TECK LAM
NRIC No	SXXXX686E
Date Of Birth	12/05/1966
Occupation	Indoor

Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

23/08/1996
26 YEARS AND 2 MONTHS
Male
(Phone) +65-96347475
-
tecklam@urban-renewables.com
289E BUKIT BATOK ST 25
#13-152
654289
No
Hirer
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Chain Collision
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?
Translator's name
Translator's ID
Translator's phone number
Translator's email
Original language used in the statement

No
4
Yes
No
Yes
2
No
-
-
-
-
-

PASSENGER 1

Name
Gender

CHIENG LII KAI
Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Traffic Police
(Phone) +65-65470000
(Fax) +65-65474900
10 Ubi Avenue 3 Singapore 408865
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?

Yes
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF2683K
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	MR TEO
Contact Number	(Phone) +65-90050323
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMV9978A
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MR LAN
Contact Number	(Phone) +65-97891579
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	FBL9052L
Vehicle Manufacturer	Honda
Vehicle Model	Cbf
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Motorcycle
Name of Driver	DANIEL CHENG
Contact Number	(Phone) +65-98150510
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	DANIEL CHENG
Gender	Male
Phone No	(Phone) +65-98150510
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	FBL9052L

re seat belts worn?
as this injured conveyed to hospital by ambulance?

No
No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for Investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: GBL 1495L
B: GBF 2683K
C: BMV 9098A
D: FBL 9052L

PIE towards Tias Affar
Zah Guan Exit

Describe Circumstance of the Accident


I was ~~driving~~ driving the van in the middle lane toward Texas with my colleague and slowed down when the vehicle in front of me slowed. I was almost came to a stop when I felt a violent jerk and a motorcyclist flew above the van and landed in front of the van. By that time the van was already came to a total stop. I went out of the van and noticed I was hit by a truck from behind and there was a motorcycle toppled between the van and the truck behind me. There was no visible injury on anyone including the motorcyclist. A passerby assisted to send the motorcyclist to the hospital..

IMPORTANT NOTE

Under General Condition – Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



SINGAPORE POLICE FORCE



T/20221028/7064

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20221028/7064

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/10/2022 19:04		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TEO TECK LAM			Address: 289E BUKIT BATOK STREET 25 #13-152 SINGAPORE 654289		
ID Type / ID No.: NRIC NO / S2635686E			Contact No.: Home/Office: Mobile: 96347475		
Nationality: MALAYSIAN			Email: TECKLAMT@GMAIL.COM		
Sex: Male	Age: 56	Date of Birth: 12/05/1966	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Head of Project			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 28/10/2022 10:10	Type of Location: Straight Road
Location: TOH GUAN ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
GBL1495L	Van					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20221028/7064

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20221028/7064

CONTINUATION OF REPORT

Driver				
Name	TEO TECK LAM		ID No.	S2635686E
Related Vehicle	GBL1495L (Van)		Contact No.	96347475
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL

Brief Details.

I was driving driving a company leased van in the middle lane PIE toward Tuas with my colleague and slowed when the vehicle (SMV9978A) in front of me slowed down. I almost came to a stop when I felt a violent jerk and a motorcyclist flew above my vehicle I was in and landed in front of me. By that time my vehicle was already came to a full stop. I went out and realized I was hit by a light commercial truck (GBF2683K) from behind and there was a motorcycle (FBL9052L) toppled on the right side behind me, which seemed to be hit by the truck too. There was no visible injury on anyone including the motorcyclist. A passerby assisted and sent the motorcyclist to the hospital. EMAS tow truck then towed my vehicle to the nearby carpark, Blk 231, Jurong East St. 21.



**SINGAPORE
POLICE FORCE**



T/20221028/7064

3 of 3

Report No. T/20221028/7064

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
TAY CHUN KEEN
Contact No.: 65476436

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
28/10/2022 19:04

Classification Of Case:

NP168