



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011031/Uvy3m4 Date: 12/12/2022 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 5719U	Veh. Inspected	FBR 1938U	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS22/3047	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	04/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA XMAX300	c.c	292	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MH3SH0847LK009586	Colour	BLUE	
Odometer	73905 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70-15	PIRELLI	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-14	PIRELLI	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/09/2022	Inspection Date	04/11/2022	
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800			
5a. Remarks				
A)REGISTRATION DATE: 16 MAR 2020 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	