



**Auto Insure Pte. Ltd.**  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SLJ8850L**

Your Ref: **SJJ37543**

Date:

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

Assessed Vehicle No : **SLJ8850R**  
Car Make and Model : **HONDA JADE**  
Date of Accident : **19/10/2022**  
Date of Assessment :

We have carried out a physical assessment of SLJ8850R at our workshop Auto Insure Pte Ltd sustained damages to the RH portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount	:	LS	
Adjusted Amount	:	\$	9,300.00
Est. Repair Days	:	6	



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by  
**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: **SLJ8850R**

Your Ref: **SJJ3754S**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<b>PARTS REPLACEMENT - LIST ITEMS</b>				
1	1	REAR FENDER RH <i>bt</i>	<i>4453</i> <i>20%</i> <u><i>3562.40</i></u>	\$ 1,280.00
2	1	REAR FENDER INNER SHIELD RH <i>de</i>		\$ 352.00
3	1	REAR FENDER LOWER GARNISH RH <i>Xnn</i>		\$ 295.00 <i>X</i>
4	1	REAR BUMPER <i>de</i>		\$ 1,827.00
5	1	REAR BUMPER SIDE BRACKET RH <i>nn</i>		\$ 143.00
6	1	REAR WHEEL RIM RH <i>see</i>		\$ <i>s/n-350</i> 890.00
7	1	REAR ABSORBER RH <i>Xnn</i>		\$ 1,042.00 <i>X</i>
8	1	REAR UPPER ARM RH <i>Xnn</i>		\$ 598.00 <i>X</i>
9	1	REAR UPPER ARM LINK RH <i>Xnn</i>		\$ 316.00 <i>X</i>
10	1	REAR TRAILING ARM RH <i>Xnn</i>		\$ 1,363.00 <i>X</i>
11	1	REAR WHEEL HUB RH		\$ 455.00
12	1	REAR WHEEL HUB BEARING RH		\$ 396.00
13	1	REAR LOWER ARM RH <i>Xnn</i>		\$ 771.00 <i>X</i>
			SUB TOTAL	\$ 9,728.00
			LESS 20%	\$ 1,945.60
			TOTAL AMOUNT	\$ 7,782.40

Our Ref: **SLJ8850R**

Your Ref: **SJJ3754S**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR FENDER INNER SHIELD CLIPS RH <i>nee</i>		\$ 30.00 <i>✓</i>
2	1	REAR BUMPER CLIPS <i>nn</i>		\$ 60.00 <i>30</i>
3	1	REAR WHEEL TYRE RH <i>Xnn</i>		\$ 280.00 <i>X</i>
			SUB TOTAL	\$ 370.00
			TOTAL PARTS COST	\$ 8,152.40 <i>60</i>

Our Ref: **SLJ8850R**

Your Ref: **SJJ3754S**

S/NO	DESCRIPTION	EST. BY WORKSHOP
<b>LABOUR &amp; PAINTWORK</b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ <del>500</del> 1,000.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ <del>120</del> 120.00 X44
3	TO CONDUCT DIGNOSIS FAULT CODE & RESET	\$ <del>80</del> 150.00
4	TO REMOVE & REFIT REAR FENDER QUARTER GLASS & MECHANISM RH	\$ <del>80</del> 150.00
5	TO REMOVE & REFIT REAR BUMPER REVERSE SENSORS	\$ <del>40</del> 100.00
6	TO CONDUCT WHEEL ALIGNMENT & BALANCING	\$ <del>60</del> 120.00
7	TO REMOVE & REFIT REAR WHEEL RIM & TYRE RH	\$ <del>40</del> 60.00
8	TO REMOVE & REFIT REAR SUSPENSION RH	\$ <del>80</del> 250.00
9	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 600.00
10	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ <del>30</del> 50.00
11	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ <del>20</del> 50.00
12	TO VACUUM, WAXING & CLEAN	\$ <del>77X</del> 50.00
13	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ <del>30</del> 50.00
TOTAL BEFORE GST		\$ 10,902.40
GST 7%		\$ 763.17
TOTAL (PARTS & LABOUR):		\$ 11,665.57

**Adjustments / Recommendations**

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 9,300.00** for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3562.40

350.00

60.00

1560.00

5532.40

20%

4425.92

h/s - \$4,400 / 6 days