

Vehicle Damage Assessment Report for [SLT6777E]

Estimate Created: 13/11/2022 22:59 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 06/12/2022 22:40 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO Insurance	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mercedes-Benz	Model	GLC
Engine Type			
License Plate Number	SLT6777E	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$5389.00 with 4 days for repair	Insurlogic 1 (06/12/2022 22:40)
- Please ignore 2022-11-14	Insurlogic 1 (06/12/2022 22:39)
- Final review base on information provide by LKK: Concluded the cost of repair at \$4626.00 with 4 days for repair	Insurlogic 1 (13/11/2022 23:09)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER		1	680.00	10.00 %	748.00
REAR BUMPER LOWER		1	550.00	10.00 %	605.00
REAR BUMPER CHROME CTR		1	350.00	10.00 %	385.00
REAR BUMPER EXHAUST CHROME		2	370.00	10.00 %	814.00
REAR EXHAUST CHROME BRACKET		1	180.00	10.00 %	198.00
REAR BUMPER SENSOR 2PCS		1	370.00	10.00 %	407.00
REAR BUMPER SENSOR HOLDERS		2	90.00	10.00 %	198.00
REAR BUMPER REINFORCEMENT		1	580.00	10.00 %	638.00
REAR BUMPER SIDE RETSINER L/R		2	180.00	10.00 %	396.00
Parts Subtotal					4,389.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE / REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	500.00	0.00 %	500.00
RNR INTERIOR UPHOLSTRY	RnR	60.00	0.00 %	60.00
RNR REVERSE SENSORS	RnR	40.00	0.00 %	40.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price	
PAINT ACCIDENT AFFECTED AREAS	Full spray	400.00	0.00 %	400.00	
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		600.00	
				Paint Labor Subtotal	400.00
				Labor Subtotal	1,000.00

Summary

Repair Cost	5,389.00
Discount(0 %)	(0.00)
	5,389.00

Excess	(0.00)
GST(0.00 %)	0.00
<hr/>	
Grand Subtotal	5,389.00