

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202222007921 Date: 29th Nov 2022

Our Ref: CS6/AIS22011076/TVY3M4

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SMF 2328G ACCIDENT ON 03/11/2022

We thank you for your instruction on 04/11/2022.

The following vehicle information was recorded:

Registration Number : SMF 2328G

Make & Model : Toyota Harrier M Grade Chassis Number : JTEZB3GH90J002723

Year of Registration : 2018 Engine Capacity : 1998 cc

- 1. The vehicle sustained damages at the front o/s portion and undercarriage. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>7 (Seven)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.