

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 3439K

at Workshop n/s CYCLE & CARRIAGE

of 188 Pinner Loop

Insured: SLJ 88C EQ1

Policy No. _____

Claims No. DM22HO01888

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 95K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lim Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLW 3439K Yr Regn: 2018 FEB

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ B160 STYLE cc 1595

Colour: GREY A/C: Insured / Std / N / NA

Sp Reading: 38345 T/Radio: Insured / Std / N / NA

Eng No: _____

C/No: WBD 2462422J468300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Medi: Nil / Shim / STD / Rim or

Tyre Size: F: 205/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

F/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 02/11/22 D.O.I. 30/11/22

Survey held at CYCLE & CARRIAGE PC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 61K

17/1/23 Rasul confirmed final fig \$15,547.40 (Red 3194.69, 20%)

Date/Time, File Pass to?

: Prefil. Report

1)

: Final Report

Date/Time, File Return to?

2) 18/1/23-typist

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Report Format : TP

Lump Sum / I.B.I.: (\$ 15,547.40)

TOTAL



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW3439K*RA

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT
5 MAXWELL ROAD #17-00
TOWER BLOCK, MND COMPLEX
SINGAPORE 069110
62239433

Vehicle & Document Information

WIP No 60735
Reg No/Reg Date SLW3439K*RA / 08/02/2018
Date In/Mileage SLW3439K*RA / 0
Chassis No WDD2462422J468300
Engine No 27091031515793
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 027 787 Mountain Gr/ 041 111 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WE000058	Credit	03/11/2022/ 18:41	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

THIS IS NOT AN OFFICIAL TAX INVOICE				
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 5130085572 // 2-11-2022 DRIVE IN/TP VEH NUMBER : 3-11-2022 // SLJ88C - EQ DATE IN/DATE SURVEY: DIRECT SETTLEMENT BY:				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.				3840 5760.00
A BPIRES RESPRAY RH/REAR DOOR & RH/REAR FENDER & RH/RUNNING BOARD & REAR BUMPER.	0.01			2802 3200.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT	0.10			380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00
A BPILAB REPLACE RIGHT REAR DOOR, TRANSFER COMPONENT PARTS				480.00
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.				960 1440.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD				60.00
A 97250001 CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM				180.00
M RH/REAR DOOR	1.00	2069.15	00.00	2069.15
M RH/REAR DOOR SEAL	1.00	313.32	00.00	313.32
M RH/REAR ABSORBING DOOR	1.00	74.42	00.00	74.42
M RH/REAR DOOR DOWEL	6.00	3.77	00.00	22.62

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.gochee@cycleandcarriage.com.sg
Cycle & Carriage Industries Pte Ltd
CUSTOMER SERVICE CENTRE Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW3439K*RA

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT
5 MAXWELL ROAD #17-00
TOWER BLOCK, MND COMPLEX
SINGAPORE 069110
62239433

Vehicle & Document Information

WIP No **60735**
Reg No/Reg Date **SLW3439K*RA / 08/02/2018**
Date In/Mileage **0**
Chassis No **WDD2462422J468300**
Engine No **27091031515793**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **027 787 Mountain Gr/ 041 111 ARTICO Leat**

SLW3439K*RA

Account No	Terms	Date/Time Printed	CSE	Operator
WE000058	Credit	03/11/2022/ 18:41	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BLIND RIVET WITH PAN HEAD	10.00	2.70	00.00	27.00
M FOOTPLATE	1.00	280.59	00.00	280.59
M RH/REAR FENDER	1.00	2702.14	00.00	2702.14
M RH/REAR DISK WHEEL	1.00	582.12	00.00	582.12
M RH/RUNNING BOARD	1.00	394.69	00.00	394.69
M CAVITY PRESERVATIVE	1.00	116.04	00.00	116.04

Done
Hp 9000068
8 days
30/11/22 @ 18:00
Resy before paint

ESTIMATE

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Go Chee Han
DID : 6771 4336 HP: 9181 7717
Email : cheehan.gochee@carriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett	18,742.09
7% GST on	18742.09
Total Payable	20,054.04

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	221B

Vehicle Details

Vehicle No.:	SLW3439K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Dec 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180 STYLE (R16 LED)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	27091031515793
Chassis No.:	WDD2462422J468300
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,732.00
Original Registration Date:	08 Feb 2018
First Registration Date:	08 Feb 2018
Transfer Count:	2
Actual ARF Paid:	\$19,425.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Feb 2028
PARF Rebate Amount:	\$14,568.00

Intended COE Rebate Details

COE Expiry Date:	07 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$19,091.00
Total Rebate Amount:	\$33,659.00

Mercedes-Benz B-Class B180 Style

Overview

[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
Price
\$95,000
Depreciation ?

\$16,450 /yr

[View models with similar depre](#)
Reg Date

09-Feb-2018

(5yrs 2mths 4days COE left)

Mileage

15,107 km (3.1k /yr)

Manufactured ?

2017

Road Tax ?

\$740 /yr

Transmission

Auto

Dereg Value ?

\$36,029 as of today (change)

OMV ?

\$26,732

COE ?

\$41,400

ARF ?

\$19,425

Engine Cap

1,595 cc

Power

90.0 kW (120 bhp)

Curb Weight ?

1,425 kg

No. of Owners ?

1

Type of Vehicle

Hatchback