

ADVANCE AUTO GARAGE

VEHICLE DETAILS

VEHICLE NO : SMX3608Y 2021 JAN
 VEHICLE MODEL : HYUNDAI AVANTE
 CHASSIS NO : KMHLN41ETMU106952

TP SMRT
 Venen

ACCIDENT DETAILS

DATE :
 TIME :

THIRD PARTY REQUESTOR / CONTACT :

XAIVER / 90079247

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Distorted</i>	1	\$ 499.70	\$ 499.70
2	FRONT BUMPER SIDE HOLDER <i>Distorted</i>	1	\$ 48.50	\$ 48.50
3	FRONT BUMPER REINFORCEMENT <i>Are new</i>	1	\$ 481.20	\$ 481.20
4	FRONT BUMPER SPONGE <i>Crushed</i>	1	\$ 119.20	\$ 119.20
5	FRONT BUMPER TOP COVER <i>Distorted</i>	1	\$ 271.80	\$ 271.80
6	FRONT BUMPER LOGO <i>New</i>	1	\$ 45.80	\$ 45.80
7	FRONT BUMPER SIDE COVER <i>cut</i>	1	\$ 124.20	\$ 124.20
8	FRONT BUMPER SIDE COVER INNER AIR DUCT <i>Crushed</i>	1	\$ 119.70	\$ 119.70
9	FRONT BUMPER LOWER GRILLE <i>Crushed</i>	1	\$ 165.40	\$ 165.40
10	FRONT BUMPER LOWER BEAM <i>Not new</i>	1	\$ 219.10	\$ 219.10
11	FRONT GRILLE <i>cut</i>	1	\$ 896.40	\$ 896.40
12	HEADLAMP <i>Crushed</i>	1	\$ 3,034.90	\$ 3,034.90
13	Headlamp Bracket <i>Crushed</i>	1	\$ 45.90	\$ 45.90
14	FRONT SUPPORT PANEL <i>Crushed & new</i>	1	\$ 949.30	\$ 949.30
15	FRONT FENDER <i>Distorted</i>	1	\$ 1,227.70	\$ 1,227.70
16	FRONT FENDER INNER SHIELD <i>torn</i>	1	\$ 195.80	\$ 195.80
17	WIPER WASHER TANK <i>Distorted</i>	1	\$ 89.40	\$ 89.40
18	WIPER WASHER TANK MOTOR <i>Not new</i>	1	\$ 126.90	\$ 126.90
19	BONNET <i>Distorted</i>	1	\$ 2,253.80	\$ 2,253.80
20	BONNET LOCK <i>New</i>	1	\$ 129.90	\$ 129.90
21	BONNET HINGE <i>New</i>	2	\$ 82.90	\$ 165.80
22	FRONT LOWER ARM <i>Best</i>	1	\$ 356.10	\$ 356.10
23	FRONT SHCK ABSORBER <i>But</i>	1	\$ 372.50	\$ 372.50
24	FRONT KNUCKLE ARM <i>Distorted</i>	1	\$ 418.20	\$ 418.20
25	FRONT WHEEL HUB C/W BEARING <i>Distorted</i>	1	\$ 296.50	\$ 296.50
26	FRONT ANTI ROLL BAR LINKAGE <i>3rd</i>	1	\$ 104.30	\$ 104.30
27	STEERING RACK & PINION <i>3rd</i>	1	\$ 1,641.90	\$ 1,641.90

TOTAL PRICE: \$ 14,399.90
 LESS 20% \$ 2,879.98
 SUB TOTAL PRICE: \$ 11,519.92

10580.50

8465.20

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00

2	FRONT GRILLE CLIPS <i>mw</i>	1 SET	\$ 20.00	\$ 20.00
3	FRONT FENDER INNER SHIELD CLIPS <i>mw</i>	1 SET	\$ 30.00	\$ 30.00
4	FRONT WHEEL RIM <i>cut</i>	1	\$ 1,000.00	\$ 1,000.00
5	FRONT TYRE <i>punctured</i>	1	\$ 280.00	\$ 280.00
6	COOLANT <i>Not m</i>	1	\$ 50.00	\$ 50.00
			TOTAL :	\$ 1,410.00

810

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	<i>700</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>600</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>50</i>	
5	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	\$ 120.00	<i>X</i>	
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	<i>X</i>	
7	TO DISMANTLE FRONT UNDERCARRIAGE	\$ 400.00	<i>220</i>	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80</i>	
9	TOWING FEES	\$ 60.00	<i>✓</i>	
		TOTAL	\$ 3,850.00	

1740

ESTIMATE REPORT

TOTAL PARTS COST: \$ 12,929.92

TOTAL LABOUR COST: \$ 3,850.00

TOTAL REPAIR COST: \$ 16,779.92

total: 11015.20

h/s: 8.8K

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

FAX:

07 Days

8.8K
07 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: