



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SGE8254Y
Chassis No : JHMRV3800NS202567
Model : HRV DX-SIN CVT YM 2022
Owner's Name : LEONG YEW KAY
Ins Policy No :
Date of Accident : 3/11/2022

Document No. : SQT22003231
Date : 3. Nov 2022
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15ZK1102567
Date | Time : 3. Nov 2022 3:11:30 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04715-3M0-000ZZ	FACE,RR.BUMPER <i>F. X M</i>	1	555.30	25	416.47	29.15	445.62
33505-TL0-G01	REAR RR ASSY,R <i>repair</i>	1	49.00	25	36.75	2.57	39.32
33555-TL0-G01	REAR RR ASSY,L <i>X M</i>	1	49.00	25	36.75	2.57	39.32
71630-3M0-003	SPACER,R.RR.BPR S <i>X M</i>	1	16.40	25	12.30	0.86	13.16
71680-3M0-003	SPACER,L.RR.BPR S <i>X M</i>	1	16.40	25	12.30	0.86	13.16
91505-TM8-003	CLIP,BUMPER <i>re /</i>	6	2.30	25	10.35	0.72	11.07
33500-3M0-J01	LIGHT ASSY,R.TAIL <i>sc /</i>	1	378.80	25	284.10	19.89	303.99
Sum Item					809.02	56.62	865.64
BOSUN	SUNDRIES	1	110.00		30 <i>✓</i>	7.70	117.70
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		180 <i>✓</i>	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		180 <i>✓</i>	17.50	267.50
BKRP21B	CUT OFF & RENEW RR FLOOR PANEL, REPAIR LH FRAME	1	1200.00		650 <i>✓</i>	84.00	1284.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1200.00		520 <i>✓</i>	84.00	1284.00
Sum Labor					3010.00	210.70	3,220.70

Survey By

Printed on 3/11/2022 3:24:07 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SGE8254Y
Chassis No : JHMRV3800NS202567
Model : HRV DX-SIN CVT YM 2022
Owner's Name : LEONG YEW KAY
Ins Policy No. :
Date of Accident : 3/11/2022

Document No. : SQT22003231
Date : 3. Nov 2022
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15ZK1102567
Date | Time : 3. Nov 2022 3:11:30 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
Date & Time	21/11/22 @ 1130						
Excess							
Status							
Signature							

Total Amount 3,819.02 267.32 4,086.34

Total (Inclusive of GST) 4,086.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/11/2022 3:24:07 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.