



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

PRO-FORMA INVOICE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No.					
			0					
			Document Date					
			15/05/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q2	05/09/2017	SLS0564Y	0	18437	66TP/SLS0564Y/071122	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU303569440		2ZRS082868	60	Shashitharan	08/11/2022	14.55	14/11/2022	9.11
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
1	Z	BP-GRAB-DS tp claim TP VEH NO.:GBD6373P ACC DATE:05/11/22 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY:08/11/22 NO OF REPAIR DAYS:4 BY:STEVE LKK AUTHORIZED ON:08/11/22				50.00		
2	B	BP-LAB2 CHECK WIRIN GAND REFOCUS HEADLAMP	*			198.00		
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL	*			1584.00		
4	B	BP-RES2 RESRPAY ACC AFF AREA	*			1312.00		
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	*			198.00		
6	B	BP-MECH2 CONDUCT WHEEL ALIGNMNET	*			198.00		
7	1	U52119-47962 COVER, FR BUMPER	1.00	560.30		560.30		
8	2	U53801-47080 FENDER SUB-ASSY, FR	1.00	1060.70		1060.70		
9	3	U53875-47070 LINER, FR FENDER, RH	1.00	223.50		223.50		
10	4	U75403-48010 EMBLEM SUB-ASSY,	1.00	77.40		77.40		
11	5	U52115-47050 SUPPORT, FR BUMPER	1.00	95.70		95.70		
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							5,557.60	
			Please acknowledge receipt of vehicle				GST 7.00%	
					Parts 2,017.60		389.03	
					Labour 3,540.00			
					Sublet 0.00			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 5,946.63	

Customer Copy