




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22011160/Rqy3m4 Date: 30/11/2022 Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMB 5021S	Veh. Inspected	SLA 5085A
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/11/22/5027	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	08/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AQUA HYBRID 1.5S A	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	NHP106425628	Colour	MAROON
	Odometer	138863 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R15	GITI	6 mm
	L/H Front Tyre	195/50 R15	GITI	6 mm
	R/H Rear Tyre	195/50 R15	GITI	6 mm
	L/H Rear Tyre	195/50 R15	GITI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	05/11/2022	Inspect Date / Time	08/11/2022 (02:24 PM)
	Survey held at	5035 ANG MO KIO IND PARK 2 #01-365		
	Repairer	CAR HUB HOLDINGS PRIVATE LIMITED		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	

Report Ref No. CS3/SMR22011160/Rqy3m4

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.