



**DICKSON GROUP**  
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

## QUOTATION

### QUOTATION FOR

NAME: Income Insurance Limited  
COMPANY NAME: Income Insurance Limited  
STREET ADDRESS: 75 Bras Basah Road, Income Centre  
POSTAL CODE: Singapore 189557  
PHONE: 6788 1777

DATE: 7 Nov 2022

REF: SLM6323T  
VEHICLE NO.: SLM6323T  
MAKE: TOYOTA  
MODEL: COROLLA  
PREPARED BY: MR POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
<b>LABOUR</b>							
1	TO REMOVE & REFIT ALL REAR LIGHTING & WIRING, TEST FOR PROPER FUNCTIONING	1		\$80.00	\$ 80.00		\$ 80.00
2	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IF NECESSARY AND REALIGN	1		\$800.00	\$ 800.00		\$ 800.00
3	TO PROVIDE SKILL LABOUR & MATERIAL TO PAINT NEW PARTS & PANELS	1		\$800.00	\$ 800.00		\$ 800.00
<b>PARTS</b>							
1	REAR BUMPER	1		\$495.00	\$ 495.00	/	\$ 495.00
2	REAR BUMPER CLIPS	10		\$5.00	\$ 50.00	30	\$ 50.00
3	REAR BUMPER SIDE RETAINER LH & RH	2		\$96.10	\$ 192.20	/ X	\$ 192.20
4	REAR BUMPER REFLECTOR LH & RH	2		\$57.60	\$ 115.20	50	\$ 115.20
5	TAIL LAMP LH & RH	2		\$338.00	\$ 676.00	//	\$ 676.00
6	RR BOOT	1		\$710.00	\$ 710.00	R X	\$ 710.00
7	RR BOOT LOGO	1		\$68.00	\$ 68.00	X	\$ 68.00
8	RR BOOT COROLLA LOGO	1		\$39.20	\$ 39.20	/	\$ 39.20
9	RR LH FENDER	1		\$955.00	\$ 955.00	R X	\$ 955.00
10	RR LH FENDER INNER SHIELD	1		\$98.50	\$ 98.50	X NN	\$ 98.50
11	RR LH FENDER INNER SHIELD CLIPS	4		\$5.00	\$ 20.00	X NN	\$ 20.00
SUBTOTAL					\$ 5,099.10	SUBTOTAL	\$ 5,099.10
GST 7%					\$ 356.94	GST 7%	\$ 356.94
TOTAL					\$ 5,456.04	TOTAL	\$ 5,456.04

### REMARKS:

Wfm 90097659

8/11/22

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

L/S Saday.

(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

FOR DICKSON AUTO CARE CENTRE PTE LTD

(AUTHORISED SIGNATURE)



Total = 1386.3

Parts

Final T: 2370

-20% = \$1,895.78

L/S \$1,900.00



**DICKSON GROUP**  
Your Trusted Automotive Solutionist

**DICKSON AUTO CARE CENTRE PTE LTD**  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

SUPPLEMENTARY QUOTATION

QUOTATION FOR

**NAME:** Income Insurance Limited  
**COMPANY NAME:** Income Insurance Limited  
**STREET ADDRESS:** 75 Bras Basah Road, Income Centre  
**POSTAL CODE:** Singapore 189557  
**PHONE:** 6788 1777

**DATE:** 8 Nov 2022

**REF:** SLM6323T  
**VEHICLE NO.:** SLM6323T  
**MAKE:** TOYOTA  
**MODEL:** COROLLA  
**PREPARED BY:** MR POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>PARTS</u>						
1	REAR END PANEL	1		\$608.10	\$ 608.10	X Dent (R)	\$ 608.10
SUBTOTAL					\$ 608.10	SUBTOTAL	\$ 608.10
GST 7%					\$ 42.57	GST 7%	\$ 42.57
TOTAL					\$ 650.67	TOTAL	\$ 650.67

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

*[Handwritten signature]* 18fm 00097659

(CUSTOMER'S SIGNATURE AND  
COMPANY STAMP)

FOR DICKSON AUTO CARE CENTRE PTE LTD

*[Handwritten signature]*



(AUTHORISED SIGNATURE)