

dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401550W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255249)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motors)



Car In
Handover

GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 NOV 2022

Estimate No. : b1 63937
Date Estimated : 07/11/2022
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Joshua Chew Shu Heng
Blk 402 Woodlands St 41
#06-134

Singapore 730402

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH8511T	WBAJA12030BJ20879	12/02/2019	5201	19513

DESCRIPTION

To replace bumper front panel, front right side panel and front attachments

1700 ✓ 3,400.00

To spray paint bumper front panel and front right side panel

1826 ✓ 1,923.00

To replace right headlight.

457 ✓ 431 481.00

To carry out body cavity preservation.
(Per panel).

112 ✓ 118.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

504 ✓ 531.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168 ✓ 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 ✓ 177.00

Sundries.

150.00

Total Labour 1: 6,957.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
FRT RH SIDE PANEL ALUMINIUM	1	952.05	952.05 ✓
COVER GRILLE RH	1	77.75	77.75 ✓
RH GRILLE AIR INLET OPEN (LINES)	1	118.75	118.75 ✓
RH PROTECTIVE STRIP LINES (LUXURY)	1	70.20	70.20 ✓
IMPACT ABSORBER TOP	1	76.15	76.15 ✓
FRT BUMPER CARRIER	1	758.85	758.85 ✓
FRT BUMPER PANEL PRIMED (PMA/PDC)	1	1,454.15	1,454.15 ✓
FRT BUMPER TOW HOOK COVER	1	53.70	53.70 ✓
SET MOUNTING PDC/PMA SENSOR FRT	1	80.55	80.55 ✓
TRIM GRILLE FRT (I CAM)	1	25.90	25.90 ✓
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	4,960.90	4,960.90 ✓

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63937
Date Estimated : 07/11/2022
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH8511T	WBAJA12030BJ20879	12/02/2019	520i	19513

DESCRIPTION	QTY	PRIC	VALUE
ULTRASONIC SENSOR IMPERIALBLAU (WA8 / cut (outer))	1	373.90	373.90
Total Parts :			9,002.85

Steve (LKK)
9/11/22, 3.00pm

m k
PIP
4 BL 4
6 Lys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,957.00
Parts	:	9,002.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,117.19
Grand Total	:	17,077.04

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **