



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22011205/Kny3e2 Date: 20/12/2022 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBC 9673J	Veh. Inspected	SHD 215G	
Policy No.	D22099240	Coverage (\$)	0.00	
Claim No.	D22003477MFCV	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	08/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC281586	Colour	METALLIC WHITE / RED	
Odometer	705430 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	7 mm	
L/H Front Tyre	215/60 R16	SAILUN	7 mm	
R/H Rear Tyre	215/60 R16	SAILUN	6 mm	
L/H Rear Tyre	215/60 R16	SAILUN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/11/2022	Inspection Date	09/11/2022	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	