

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 16 February 2023 8:09 AM
To: geraldph@lonpac.com
Cc: MT_Claim_SG; Admin A
Subject: [SEEK MANDATE] - Your ref: 22/22/22/VC05/026541 // LKK ref : CC4/LPC22011217/Rpa3q2 [ACCIDENT INVOLVING YQ9696Y(LONPAC) AND SMW307R(TP) ON 07/11/2022]
Attachments: TP GIA REPORT.pdf; LKK SURVEY REPORT & PHOTOS.pdf; SMW307R LOD.pdf

Your ref: **22/22/22/VC05/026541**
LKK ref : CC4/LPC22011217/Rpa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING YQ9696Y(LONPAC) AND SMW307R(TP) ON 07/11/2022

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not on our driver favour.

We seek your approval to offer repairer **"KAH MOTOR.CO.SDN.BHD"** at **\$12,410.37(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (with 7% GST)	\$ 18,395.11	\$ 11,688.37 (\$10,923.71 + 7% GST)
2. Loss of Use (12days x \$60.00)	\$ 720.00	\$ 720.00 (12DAYS X \$60.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 19,117.11	<u>\$ 12,410.37</u>

Surveyor recommended 9days for repair + 2SUNDAY + 1PRS = 12DAYS.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 15/02/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

