

Kah Motor Co. Sdn. Bhd. (A Member of Oriental Holdings Rethad Body Repair & Paint Centre 6A Mandai Estate Singapore 729903

Tel: +65 6841 3838 Fax: +65 6362 5015 www.honda.com.sg

M/s: Lonpac Insurance Bhd

C/o LKK Auto Consultants Pte Ltd Blk 51 Paya Ubi Industrial Park #02-25

Singapore 408933

Attn: Motor Claims Department

Ms Hsiao Tong

Date

**Your ref**: CC4/LPC22011217/pa3

Our ref : SMW307R

11/1/2023

Dear Sir / Madam,

#### THIRD PARTY DIRECT SETTLEMENT

## ACCIDENT INVOLVING SMW307R & YQ9696Y DOA: 07/11/2022

We refer to the item(s) marked ( ✓ ) below:

(	V	)	we refer to your fax dated 11/11/2022.
(	V	)	We enclosed herewith the repair invoice / Third Party Direct Settlement Agreemen

Kindly forward the discharge voucher for our client's signature within 2 weeks via email to : desmondtoh@honda.com.sg

We return your discharge voucher duly completed.

Kindly expedite settlement the following:-

Repair Cost

S\$ 11,688.38 payable to Kah Motor Co. Sdn. Bhd.

Loss of Use

S\$ 60.00 x 12 days = S\$ 720.00

payable to Hua Meiting

(2 PRI + 8 Working Days + 2 Sun)

GIA Search

S\$2.00 payable to Kah Motor Co. Sdn. Bhd.

 $( \checkmark )$ Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.

Letter of Authority ( 🛂 )

Thank you.

Yours faithfully,

Anikka Lai

# **LETTER OF AUTHORITY**

## TO WHOM IT MAY CONCERN

ACCIDE	NI INVOLVING (OWNER	VEHICLE NO.)	SM N	/30/R	8c
(THIR PA	ARTY'S VEHICLE NO.)	YQ9696Y	ON _	7/11/2022	
ALONG	WOODLANDS AVE 4				
	authorize Kah Motor Co. uthorized by Kah Motor t			-	
<b>**</b> 5	To submit, resolve and rethe 3rd party insurers.	make any claim(s)	which I may	have against	
=:	To execute, sign dischard documents in connection		•		7
<del>5</del> 2.0	Any payment should be Sdn Bhd.	made in favour of	my name / K	Cah Motor Co.	
	₩,				
Owner Sig	gnature				
(Co stamp	& authorized signature if is (	Co registered vehicle)	)		
Name:	HUA MEITING				
Nric No:	S9245457F				
Veh No:	SMW307R				
Date:	12/11/2022				



# LONPAC INSURANCE BHD

CLAIM NO

£ 22/22/22/VC05/026541

DATE

: 02 MARCH 2023

WITHOUT PREJUDICE to:

## DISCHARGE VOUCHER

Any Personal Injury Claims

I/We, HUA MEITING confirmed acceptance from M/s LONPAC INSURANCE BHD and/or owner of YQ9696Y the sum of Singapore Dollar Twelve Thousand Four Hundred Ten and Cents Thirty Seven Only (\$12,410.37) in full and final satisfaction, liquidation and discharge of all property losses competent to me/us upon the said M/s LONPAC INSURANCE BHD in respect of all property losses sustained by me/us whether now or hereafter to become manifest, arising either directly or indirectly from an accident involving SMW307R and YQ9696Y on 07/11/2022 along/at WOODLANDS AVE 4.

I /We hereby agree to indemnify and keep indemnify (LONPAC INSURANCE BHD/ QI FU ENTERPRISE CO PTE LTD AND/OR LEE YOON LEONG) against all claims and any claims whatsoever made by any person/persons on our behalf in respect of the said accident.

I/We further authorize you to pay the above settlement sum directly to "KAH MOTOR.CO.SDN.BHD".

I/We hereby acknowledged that this payment is made on a without admission of liability basis and without prejudice to all related claims and in respect of our insured's recovery action.

07/03/2023

Signature of vehicle owner/Date

HUA MEITING 07/03/2023

Name of vehicle owner /Date



#### Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad) 6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No : +65 6841 3838 Fax No :

LONPAC INSURANCE BHD MOTOR CLAIMS DEPT 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE, 199555

Customer Code: CU0129752

## Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

SINV-BM22001257

Invoice Date Order No.

Invoice No.

31/12/22 SVO22049969

Reference Job Card No.

14487 08/11/22 / 6:44:23 PM

Date/Time Received 3 Licence No.

SMW307R JAZZ 1.3LXR CVT 20YM

Model Car Chassis No. Car Engine No.

JHMGK3850LS218306 L13B15001052

Mileage Service Advisor 12855

Served By Page

:

: ANIKKA LAI SWEE KAM 1821 **ANIKKALAI** 

1

N.		(125 - 4 best (25 cost)) - cos	22721	274				7% GST Am	ount incld
No.		Description TR DIPEOT OF THE SAFETY (1910)	Qty.	UoM	U. PriceD	isc %	Amount	Amount	GST
		TP DIRECT SETTLEMENT (J/NO:	)						
		OWNER: HUA MEITING							
		OWNER INSURER: LIBERTY							
		ACC DATE: 07/11/2022							
		SURVEYED BY: RASUL / LKK							
		DATE: 09/11/2022							
		REF NO: CC4/LPC22011217/pa3							
		TP INSURER: LONPAC							
00400 TEA 144077		TP VEH: YQ9696Y							
68100-T5A-U10ZZ		TAIL GATE COMP	1	Each	782.10	25	586.57	41.06	627.63
74440-T5A-003		WEATHERSTRIPTAILGATE	1	Each	92.30	25	69.22	4.85	74.07
75722-T5L-T01		EMBLEMRR.	1	Each	12.50	25	9.37	0.66	10.03
74890-T5A-A11		GARNISH ASSY,RR LICENCE	1	Each	112.90	25	84.67	5.93	90.60
75701-T5A-000		EMBLEMH	1	Each	10.70	25	8.02	0.56	8.58
90301-ST0-003		NUT,PUSH 3MM	2	Each	2.10	25	3.15	0.22	3.37
33500-T5A-J02		TAILLIGHT ASSY,R.	1	Each	258.40	25	193.80	13.57	207.3
33550-T5A-J02		TAILLIGHT ASSYL.	1	Each	258.40	25	193.80	13.57	207.37
04715-T5A-J50ZZ		FACE,RR.BUMPER	1	Each	496.90	25	372.67	26.09	398.76
71593-T5A-J50		SPACER,R.RR.BUMPER SIDE	1	Each	18.10	25	13.57	0.95	14.52
71598-T5A-J50		SPACER,L.RR.BUMPER SIDE	1	Each	18.10	25	13.57	0.95	14.52
71505-T5A-J50		GARNISH,RR.BUMPER	1	Each	41.00	25	30.75	2.15	32.90
66100-TAR-T00ZZ		PANEL COMPRR.	1	Each	342.90	25	257.17	18.00	275.17
76720-T5A-003		ARMRR.WIPER	1	Each	45.60	25	34.20	2.39	36.59
76721-T5A-003		COVERARM	1	Each	5.70	25	4.27	0.30	4.57
76730-T5A-003		BLADERR.WINDSHIELD WIPER 350M	1	Each	43.90	25	32.92	2.30	35.22
NMDVR-NEFUPLAB	O-	DVR, NEFU PLABO 2 CHANNEL NEW	1	Each	330.00		330.00	23,10	353.10
2CPN									
BOSUN	1466	SUNDRIES	1	Hours	50.00		50.00	3.50	E2 F
BG02R	1757	REPLACE RR. WINDSCREEN.(N)	1	Hours	650.00		650.00	45.50	53.50
BML02I	1757	INSPECT RR LIGHTING MECHANISMS.	1	Hours	180.00		180.00		695.50
		PERFORM WATER TEST.(N)	ı	riours	100.00		160.00	12.60	192.60
BA02R	1757	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	180.00		180.00	12.60	192.60
3G01S	1757	TO VACUUM & CLEAR SHATTERED GLASS	1	Hours	380.00		380.00	26.60	406.60
BKTG02R	1757	REMOVE & TRANSFER ITEMS TO NEW	1	Hours	380.00		380.00	26.60	406.60
		TAILGATE. ADJUST & ALIGN TAILGATE.(N)			<del>-</del>		555,50	20.00	400.00
3C011R	1757	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	Hours	380.00		380.00	26.60	406.60

Printed by ANIKKALAI on 11 Jan 2023 at 3:04:34 PM

This is a computer generated invoice. No signature is required, Please review your bill and advise us of any errors or omissions, Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s),



## Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No.: +65 6841 3838 Fax No.:

LONPAC INSURANCE BHD MOTOR CLAIMS DEPT 300 BEACH ROAD #17-04/07 THE CONCOURSE

SINGAPORE, 199555

Customer Code: CU0129752

## Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. SINV-BM22001257 Invoice Date 31/12/22 SVO22049969 Order No.

Reference

14487 Job Card No.

08/11/22 / 6:44:23 PM Date/Time Received Licence No. SMW307R JAZZ 1.3LXR CVT 20YM Model

JHMGK3850LS218306 Car Chassis No. L13B15001052 Car Engine No.

12855 Mileage ANIKKA LAI SWEE KAM 1821 Service Advisor

Served By **ANIKKALAI** 2

Page

		B	Otte	UoM	U. PriceDi	ico 9/	Amount	7% GST Am Amount	ount incld GST
No.	4757	Description REMOVE & INSTALL CAR VIDEO CAMERA	Qty.	Hours	380.00	SC /a	380.00	26.60	406.60
BC011R	1757	WITH POWER SAVER	1	Hours	360.00		300.00	20.00	700,00
BMI03D	1757	REMOVE & INSTALL REAR COMPARTMENT	1	Hours	325.00		325.00	22.75	347.75
DIVIIO3D	1101	LININGS	·						
		GARNISHES.(N)							
BOJSE	1757	BODY JOINT SEALANT TAILGATE	1	Hours	80.00		80.00	5.60	85.60
BKRP02S	0671	STRAIGHTEN ALIGN RR PANEL & RENEW	1	Hours	2,600.00		2,600.00	182.00	2,782.00
		DAMAGE PARTS.							
BP05R	1718	SPRAY PAINTING ON REPAIRED OR	1	Hours	2,080.00		2,080.00	145.60	2,225.60
	1.100	REPLACED AREAS.(5P)	1	Hours	100.00		100.00	7.00	107.00
BO-TOW	1466	TOWING SERVICES (MBBS)	1	Hours	100.00		100.00	7.00	101.00
73211-T5A-J01		GLASS SETRR.WINDSHIELD	1	Each	625.60	25	469.20	32.84	502.04
73127-TY0-000		RUBBER CWINDSHIELD DAMPER	1	Each	12.30	25	9.22	0.65	9.87
73214-T5A-013		RUBBERWINDSHIELD DAMPER	2	Each	7.60	25	11.40	0.80	12.20
73226-SZW-000		DAMPERSTD 5X5	1	Each	9.10	25	6.82	0.48	7.30
BO-WS-SEALANT		WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40
76711-T5A-003		CAPPIVOT	1	Each	5.80	25	4.35	0.30	4.65
76711-13A-003		CALLIVOT		Lacii	0.00				
BO-R-COOL-RWS		SUPPLY & INSTALL SOLAR FILM ON REAR	1	Labor	300.00		300.00	21.00	321.00
		WINDSCREEN							
			Sum	Labor			7,765.00	543.55	8,308.55
				Item			2,858.71	200.12	3,058.83
					l Services		300.00		321.00
			Sum	Externa	Services		300.00	21.00	32 1,00
			Tota	I SGD			10,923.71	764.67	11,688.38
			Tota	l Payable	e (SGD)				11,688.38

INSURER ENQUIRY

# Find insurer

Vehicle reg. no.

YQ9696Y

**Date of Accident** 

07/11/2022

Reset

## % RESULT & RECEIPT

5MW 307R

TP Insurer Enquiry						
Insurance	Lonpac Insurance Bhd					
Period of Insurance	01/07/2022 - 30/06/2023					
Requested By	CHOW YUEN CHEE WINSON (K					
Requested Date	08/11/2022 16:44					

## **Payment details**

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13** 

Total Amount Due (GST Inclusive): **\$\$2** 

#### **General Insurance Association**

Records Management Centre
GST Registration No: M400017735

## **Hsiao Tong (LKKAuto)**

Sent: Thursday, 16 February 2023 9:50 AM

**To:** Hsiao Tong (LKKAuto)

Cc: MT\_Claim\_SG

**Subject:** RE: [SEEK MANDATE] - Your ref: 22/22/VC05/026541 // LKK ref:

CC4/LPC22011217/Rpa3q2 [ACCIDENT INVOLVING YQ9696Y(LONPAC) AND

SMW307R(TP) ON 07/11/2022]

## Lonpac External - General

Dear Hsiao Tong,

Please proceed as proposed.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road, #17-04/06 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

We are committed to acting professionally, fairly and with integrity. We do not condone bribery, fraud or corrupt practices.

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Thursday, February 16, 2023 8:09 AM

To: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Cc: MT\_Claim\_SG <mt\_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: [SEEK MANDATE] - Your ref: 22/22/22/VC05/026541 // LKK ref: CC4/LPC22011217/Rpa3q2 [ACCIDENT

INVOLVING YQ9696Y(LONPAC) AND SMW307R(TP) ON 07/11/2022]

Your ref: **22/22/22/VC05/026541** LKK ref: CC4/LPC22011217/Rpa3q2

Dear Sirs/Mdm,

#### ACCIDENT INVOLVING YQ9696Y(LONPAC) AND SMW307R(TP) ON 07/11/2022

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not on our driver favour.

We seek your approval to offer repairer "KAH MOTOR.CO.SDN.BHD" at \$12,410.37(all-in).

The summary is as follows: -

Amount Claimed	Amount Revised
----------------	----------------

1. Cost of Repair (with 7% GST)	\$ 18,395.11	\$ 11,688.37 (\$10,923.71 + 7% GST)
2. Loss of Use (12days x \$60.00)	\$ 720.00	\$ 720.00 (12DAYS X \$60.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 19,117.11	<u>\$ 12,410.37</u>

Surveyor recommended 9days for repair + 2SUNDAY + 1PRS = 12DAYS.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 15/02/2023 is only for mandate purpose.

### Kindly let us have your approval / instruction.

Best Regards,

 $\textbf{Hsiao Tong, Chew (Ms)} \mid \textbf{Case Handler}$ 

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> |

HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)