



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011241/Rvy3m4	
			Date: 21/02/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 1468M	Veh. Inspected	SLQ 8989M	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/11/22/5011	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	09/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. X3 M40I HL	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	WBATY920109F49872	Colour	BLUE	
Odometer	20935 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/35 R21	BRIDGESTONE	6 mm	
L/H Front Tyre	275/35 R21	BRIDGESTONE	6 mm	
R/H Rear Tyre	275/35 R21	BRIDGESTONE	6 mm	
L/H Rear Tyre	275/35 R21	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/11/2022	Inspection Date	05/12/2022	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	