|--|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio	nale Des Experts En Auto	mobile	
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CS3/CTI22011242/Swp3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date	e: 09/11/2022	
			Cod	e: CTI	
1.		AIM)			
	Insured Veh.	SMM 1998S	Veh. Inspected	SMU 1333T	
	Policy No.	DMPCSNW00183032200	Coverage (\$)	0.00	
	Claim No.	SNM22D208040/C02	Excess (\$)	0.00	
	Assign From	ADELINE CHNG	Assign Date	09/11/2022	
2.		Vehicle Partic	culars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer -		Steering		
	Brakes		Modification		
	General				
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
5.	General Information				
	Accident Date	07/11/2022	Inspection Date	09/11/2022	
	Survey held at	GARAGE 13 PTE LTD			
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				