



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011243/Uvy3m4 Date: 22/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHF 385M	Veh. Inspected	SMV 8808P	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/11/22/2011	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	09/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA 200 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD1173432N072518	Colour	WHITE	
Odometer	143898 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/11/2022	Inspection Date	09/11/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	