

ASS. REC. BY:

REF:

CTU 22 011246

1Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMHCSNW00002032200

Claims No. SNM22D207961/C01/TANCHC

Sum Insured:

Excess:

1250

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

8173k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Will have Supplement

17/4/23 Final fig \$5975.24 confirmed by email (Red 757, 11%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

17/4-23-typist

Report Format: Merimen

ump Sum / I.B.I: (\$ 5975.24

Veh No:

SND 7658

Tr Regn:

01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

Pienta

c.c

1496

Colour

m.p. white

A/C:

Insured / Std / NI / NA

Sp. Reading

54080

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NHPI70

7251043

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

2

mm

L/Bal.

6

mm

L/Bal.

2

mm

D.O.A.

3/11/22

D.O.I.

9/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation

S - RS, SI

Fees

Others

TOTAL

Goldbell Engineering Pte Ltd
8 Tuas Ave 18, Singapore
638892

Insurer Reference: **SND7658U**
Repairer Reference: **SND7658U**
Date calculated: **07/11/2022 3:53 PM**

Full Report
Registration: SND7658U
Printed: 07/11/2022 3:53 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Kon Yin Siew	Currency:	SGD
Claim Reference:	SND7658U	Date of Incident:	03/11/22
Estimated Repair Time:	7	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	SIENTA		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 T2 01		
Registration:	SND7658U		
VIN number:			
Odometer:	54080		
Model Specs			
FROM 03.2017	AIR CONDITIONING	DOOR MIRROR PAINTED	RADIO
LED HEADLAMP	7 SEATS	SIDE WINDOW TINTED	COLD WEATHER PACKAGE
CRUISE CONTROL	ELECT SLIDING DOORS	1.5 LTR 79 KW	TYRE PRESSURE CHECK
TYRES 185/60 TR 15	WHEELS 6J X 16 ALU	FRONT DRIVE	SIDE AIRBAG
PREPARE OFF VEHICLE	CLEAR COAT HARD	BASECOAT CLEAR	

*Not Withheld
Return B & P
Ex 812501*

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Code	Description	WU	Price SGD
420091)	R + R L/F WHEEL/TYRE	2.0	8.40
473101)	DETACH + REFIT FRONT BRAKE CALIPER	2.0	8.40
431011)	R + R FRONT CONTROL ARM	5.0	21.00
431151)	DISS/ASS L/F UPPER SUSPENSION STRUT	1.0	4.20
431151)	DISS/ASS FRONT LOWER SUSPENSION STRUT	1.0	4.20
431151)	R + R L/F SHOCK ABSORBER	5.0	21.00
431101)	RENEW L/F COIL SPRING	6.0	25.20
431611A	DETACH + REFIT LEFT FRONT STABILIZER	1.0	4.20
NO NUMBER	R + R FRONT AXLE CARRIER	7.0	29.40
431011)	RENEW L/F LOWER AXLE LINK (REMOVED)	2.0	8.40
431611)	R + R STABILIZER BRACKET	3.0	12.60
434601)	DETACH + REFIT FRONT DRIVE SHAFT	2.0	8.40
434601)	R + R FRONT DRIVE SHAFT	9.0	37.80
434211)	R + R L/F STEERING KNUCKLE	3.0	12.60
434211)	RENEW L/F STEERING KNUCKLE (REMOVED)	5.0	21.00
NO NUMBER	ADD/WORK R + R FRONT STEERING KNUCKLE/S	5.0	21.00
042214)	BALANCE WHEEL/S	1.0	4.20
0471	BONNET REPAIR	20.0*	84.00
0475	L/BONNET HINGE REPAIR	na 5.0* x	21.00
0476	R/BONNET HINGE REPAIR	na 5.0* x	21.00
1481	LEFT FRONT DOOR REPAIR	20.0*	84.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		14.00	140.0
Total of Labour			588.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - BASECOAT CLEAR	WU	Price SGD
	L/F WING NEW PART PAINTING	9.0	
	L/FR WHEEL NEW PART PAINTING	6.0	
	FRONT BUMPER NEW PART PAINT K1R	13.0	
	BONNET REPAIR PAINTING >50%	19.0	
	LEFT FRONT DOOR REPAIR PAINTING >50%	24.0	

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	17.00
7201	L/FR WHEEL NEW PART PAINTING	4.10
0281	FRONT BUMPER NEW PART PAINT K1R	62.90
0471	BONNET REPAIR PAINTING >50%	22.10
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	33.10

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			71.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	10.10	101.0	424.20

Material Cost - Paint
 New Part Painting
 New Part Painting - Plastic K1R
 Repair Painting
 Material-constant Metal Preparation
 Material-constant Plastic
Total

Price SGD
 21.10
 62.90
 55.30
 28.60
 9.00
 177.04

Spare Parts

prices as at 2015-06-01/01

Code	Description	Part Number	Part Source	Price SGD
0255	L/F LOWER BUMPER LID	81482 0D290	Original	70.00
0281	FRONT BUMPER	52119 0U928	Original	220.00
0317	L/F BUMPER BRACKET	52144 0D120	Original	40.00
0561	LEFT HEADLAMP ASSY	81150 52K30	Original	450.00
0741	L/F WING	53812 0D220	Original	250.00
0841	L/F WHEELHOUSE COVER	53876 0D410	Original	85.00
7035	L/DRIVE SHAFT CPL	43420 0D460	Original	585.00
7053	L/LWR AXLE STEERING	48069 09270	Original	290.00
7077	L/FR SHOCK ABSORBER	48520 0D370	Original	260.00
7081	L/F STEERING KNUCKLE	43212 0D290	Original	280.00
7091	L/UPP SUPP MOUNTING	48609 0D150	Original	85.00
7201	L/FR WHEEL	42611 0DD30	Original	300.00
7227	L/FR TYRE	185/60 R 15.. T/Y	Original	150.00
7271	L/F STABI LINKAGE	48820 0D040	Original	85.00
7300	POWER STEERING CPL	45510 0D560	Original	660.00
7311	L/TIE ROD BALL JOINT	45047 09390	Original	60.00
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				3,870.00
Total				3,870.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	3,870.00	3,870.00
Labour Time Base 10 WU/h		
Total 140.0 WU X 42.00 SGD/h		
Total of Labour	588.00	588.00
Paint Work Time Base 10 WU/h		
Labour Cost 101.0 WU X 42.00 SGD/h		
Material Cost	424.20	
Total Paint Including Material	177.04	601.24
Repair Cost Excludes GST		5,059.24
GST (+7.0%)		354.15
Repair Cost Included GST		5,413.39

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me, or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(a) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Representative of the Person(s)
(Name as in NRIC/ID card)

Sketch Plan

Mandalay Rd.



SNP7658U

SDV1221J

G^o SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This statement must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate your claim.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/11/2022 19:13 (SGT)
Reported by	Both
Date of Accident	03/11/2022 21:40 (SGT)
Exact Location of Accident	Mandalay Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SND7658U
-----------------------------	----------

INSURED POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG SUN GIAP (HUANG SHANYE)
NRIC No	SXXXX998F
Email Address	ALEXNGIRRITING@GMAIL.COM
Mobile Phone No	(Phone) +65-82841461
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Sienta
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMHCSNW00002032200

DRIVER

Name of Driver	NG SUN GIAP (HUANG SHANYE)
NPIC No	SXXXX998F
Date Of Birth	14/07/1982
Occupation	Indoor

[Back to OneMotoring](#)

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

998F

Vehicle Details

Vehicle No.:

SND7658U

Vehicle to be Exported:

Yes

Intended Deregistration Date:

06 Nov 2022

Vehicle Make:

TOYOTA

Vehicle Model:

SIENTA HYBRID 1.5X CVT

Primary Colour:

White

Manufacturing Year:

2021

Engine No.:

1NZ9327040

Chassis No.:

NHP1707251043

Maximum Power Output:

73.0 kW (97 bhp)

Open Market Value:

\$24,455.00

Original Registration Date:

24 Jan 2022

First Registration Date:

24 Jan 2022

Transfer Count:

0

Actual ARF Paid:

\$11,237.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

23 Jan 2032

PARF Rebate Amount:

\$8,427.00

Intended COE Rebate Details

COE Expiry Date:

23 Jan 2032

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$55,001.00

COE Rebate Amount:

\$44,000.00

Total Rebate Amount:

\$52,427.00

The information contained herein is correct as at 06 Nov 2022

OK