

19 X

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Vehicle No : SLV5722P
 Chassis No : _____
 SA Name : _____
 Model Year : _____

Quotation No : 0000637115
 Date : 14/11/2022
 Time : 11:59:15
 Page : 1
 Partsman : p13tansb
 Del Doc : 004551590

/N	PART NUMBER	DESCRIPTION	STK PDC ISS.			SELLING PRICE	DIS %	NET PRICE
			CT	AT	SOH			
**	*****	*****	**	***	***	*****	*****	*****
1	61667006063	STRAINER FOR WASH	—	P	—	1	6.85 / <i>MC</i>	6.85
2	51767300518	FRT RH FENDER SEAL	—	P	—	1	34.55 / <i>CR</i>	34.55
3	13718601677	INTAKE SILENCER	—	P	—	1	513.65 / <i>BR</i>	513.65

Steve (LKK)
15/11/22

SA Signature : _____
 Date : _____
 Time : _____

Parts Total : 555.05
 Labour Charges : _____
 Sub Total : _____
 Add 7% GST : _____
 TOTAL AMOUNT : _____

Customer's Name : _____
 Contact Person : _____

- Note: (1) The above quotation is based on visual inspection only and may change based on further checks.
 (2) The validity of this quotation is 14 days from the above date.
 (3) Parts are subject to availability.
 (4) Any prices change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for us to proceed with the job on the understanding that prior approval will be obtained from you before we carry out any further repair or replacement of parts that will extend the total charges beyond the sum stated.

SLU5722P

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401555M GST Reg. No M2-0020081-X
Toll-free Number (1800-2255244)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kembangan Road
East Coast Centre
Singapore 430160
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64744201 (AfterSales)
64744224 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

1713609

Page No. : 1 of 6

Estimate No. : b1 63836
Date Estimated : 28/10/2022
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -

Wong Tiong Pern (Wang Zhangpeng)
6 bishan street 25 #33-16
#33-16

Singapore 573975

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU5722P	WBA2D920405E91321	07/12/2017	216i G TOURER	43707

DESCRIPTION

VALUE

To tow accident vehicle to PML workshop.

150.00

To replace front bumper, front center air duct, front left & right support
strut, cross link, right headlight inner support and to knock out dented
are

1709 3,400.00

To respray front bumper and right fender

1826 1,923.00

To replace charge air cooler including conduct check for leak and proper function.

504 531.00

To replace left headlight.

? 481.00

To replace right headlight.

456 481.00

To replace air con condenser and air con hose including
vacuum system, top up freon gas and conduct check for
leak. (For all models except for 7 series).

952

? 1,003.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 177.00

To check electrical wiring system at the front section
for proper function including adjustment of headlights.

168 177.00

To supply front emboss number plate.

78 83.00

Sundries.

150.00

(* pls sent the chassis repair & remove engine & Bench)
(1 labour list)

Total Labour 1:

8,556.00

RH EXTENSION WHEEL HOUSING STRUT

1 173.00

173.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

260, Tampong Arang Road
East Coast Centre
Singapore 438160
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64794401 (AfterSales)
64794424 (Motorsrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 6

Estimate No. : b1 63836
Date Estimated : 28/10/2022
Prepared By : Han Kwan Yong

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE
SLU5722P WBA2D920405E91321 07/12/2017 2161 G TOURER 43707

DESCRIPTION	QTY	PRIC	VALUE
RH CROSS SUPPORT SIDE PANAL	1	33.85	33.85
LH VERTICAL STRUT	1	49.50	49.50
RH ADAPTER BOTTOM	1	82.10	82.10
FRT CROSSLINK	1	114.85	114.85
FRT IMPACT ABSORBER	1	83.45	83.45
FRT LH BOTTOM DEFORMATION ELEMENT	1	91.60	91.60
FRT RH BOTTOM DEFORMATION ELEMENT	1	91.60	91.60
FRT BUMPER BOTTOM CARRIER	1	156.00	156.00
# FRT FLAP TOWING EYE PRIMED	1	43.95	43.95
GRILLE BUMPER MIDDLE CLOSED (PDC)	1	121.15	121.15
RH FINISHER (LUXURY LINE)	1	79.95	79.95
LH ROD	1	24.65	24.65
RH ROD	1	24.65	24.65
RH SUPPORT FOG LAMP (GESCHLOSSEN)	1	24.65	24.65
FRT LH TOP DEFORMATION ELEMENT	1	80.55	80.55
FRT RH TOP DEFORMATION ELEMENT	1	106.75	106.75
# FRT BUMPER PANEL PRIMED (PMA)	1	106.75	106.75
RH GRILLE SIDE OPEN (LUXURY LINE+PD)	1	950.80	950.80
FRT BUMPER TOP CARRIER	1	96.95	96.95
RH VERTICAL STRUT	1	400.80	400.80
LICENCE PLATE HOLDER	1	49.50	49.50
FRT LH GRILLE (LUXURY)	1	74.50	74.50
FRT RH GRILLE (LUXURY)	1	119.35	119.35
GROMMET	1	119.55	119.55
RH SUPPORT HEADLIGHT ARM	2	0.80	1.60
LH BOTTOM ADAPTER	1	78.50	78.50
MOUNTING WASHER FLUID RESERVOIR	1	102.30	102.30
LH SUPPORT	1	12.95	12.95
RH SUPPORT	1	155.70	155.70
FRONT CROSSLINK	1	155.70	155.70
FRONT PANEL V STRUT	1	129.50	129.50
# FRT RH WHEEL ARCH COVER	1	126.80	126.80
TAIR DUCT	1	138.40	138.40
UNDERBONNET SCREEN	1	276.05	276.05
RH GASKET HEADLIGHT AND HOOD	1	191.95	191.95
PLAQUE 82MM	1	19.90	19.90
FRT ENGINE HOOD SEALING	1	72.85	72.85
WASHER FLUID RESERVOIR	1	52.85	52.85
LH HEADLIGHT LED TECHNOLOGY	1	136.80	136.80
RH HEADLIGHT LED TECHNOLOGY	1	2,399.10	2,399.10
RH FOG LIGHT	1	2,399.10	2,399.10
CONDENSER AIR CONDITIONING WITH DRI	1	306.85	306.85
ULTRASONIC SENSOR BLACK	1	1,032.05	1,032.05
DECOUPING RING PDC TORQUE CONVERTER	2	254.05	508.10
	2	5.30	10.60

Total Parts : 12,176.00