

ASS. REC. BY:

REF:

072 / 22011272/kn

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 815,500k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

PJP2542L Yr Regn: 03, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Sub Swift

c.c

1328

Colour:

M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading

151625

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JSAE7C11P00550550

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

1/11/22

D.O.I.

10/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation

S - RS. \$

F. m. s

Others

Report Format :

mp Sum / I.B.I: (\$

TOTAL

A314-32-C6Z5



Gigabit

Weekend (\$

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Not Authorised

11 Day &

Puting After Pain

10 days

No. : 32627

Date : 08-Nov-2022

Vehicle Insured : SLJ 8719 M

Accident Date : 01-Nov-2022

Our Ref : 022384 (CHINA) / ANGIE

PAGE : 1

NEO SAY BENG (MR)
Singapore

ESTIMATED COST OF REPAIR FOR SUZUKI SWIFT 1.3 AT (1328cc) (2009) SJP2542L

1 pc front bumper		1,011.30 ✓
2 pcs front bumper side retainer - (LH/RH)	@ S\$ 23.70	47.40 ✓
1 pc front bumper centre lower grille		89.05 X
1 pc front bumper tow cover		27.01 ✓
1 pc front bumper lower reinforcement		239.10 X
1 pc front bumper lower reinforcement garnish		288.55 X
1 pc front bumper upper reinforcement		277.08 ✓
1 pc front bumper upper reinforcement garnish		324.05 ✓
10 pcs front bumper clips	@ S\$ 5.00	50.00 ✓
1 pc RH front bumper fog cover		145.75 ✓
1 pc front grille		112.70 ?
1 pc front grille logo		17.35 ?
2 pcs headlamp assy (LH/RH) <i>cl/Br</i>	@ S\$516.05	1,032.10 ✓
2 pcs RH headlamp back cover <i>cl/mil</i>	@ S\$ 36.40	72.80 ✓
1 pc RH headlamp wireharness		
1 pc RH headlamp panel		128.65 ✓
1 pc RH front fender		379.25 ✓
1 pc RH front fender inner bracket		23.10 ✓
1 pc RH front fender inner vertical garnish		35.20 ?
1 pc RH front fender inner shield		78.05 ✓
8 pcs RH front fender inner shield clips	@ S\$ 5.00	40.00 ✓
1 pc RH front fender inner panel		401.25 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SLJ 8719 M
Our Ref : 022384

Page : 2

No. : 32627

1 pc	RH front fender wheel housing panel		367.15	7
1 pc	RH front fender lamp		18.00	X
1 pc	bonnet		747.50	✓
2 pcs	bonnet hinges (LH/RH)	old dir @ S\$ 24.75	49.50	4
1 pc	bonnet outer chrome		26.00	X
1 pc	bonnet lock		63.25	X
8 pcs	bonnet insulation clips	@ S\$ 5.00	40.00	X
1 pc	bonnet stand bush		6.00	X
1 pc	bonnet stand clip holder		6.00	X
1 pc	front support panel		580.95	7
1 pc	air con condenser		791.50	X
1 pc	radiator		890.40	X
1 pc	RH radiator side garnish		26.35	X
1 pc	RH radiator air guide		21.00	X
1 pc	air con discharge pipe		125.90	7
1 pc	wiper washer tank	]	98.40	✓
1 pc	wiper washer tank neck			
2 pcs	wiper washer tank motor	@ S\$152.80	305.60	✓
1 pc	RH front lower arm		218.75	7
1 pc	RH front knuckle arm		343.55	7
1 pc	RH front knuckle arm bearing		70.35	7
1 pc	RH front bearing hub		184.15	7
1 pc	RH front shock absorber		236.40	7
1 pc	RH front shock absorber stopper		30.55	7
1 pc	RH front shock absorber bearing		23.60	7
1 pc	RH front stabilizer bar linkage		59.95	7
1 pc	RH front tie rod end		95.10	X
1 pc	RH front tie rod		105.05	X
1 pc	RH front drive shaft		659.60	7
1 pc	steering corss member		549.65	7
1 pc	steering rack & pinion		1,874.55	7
1 pc	engine mounting - RH		154.45	7
1 pc	engine mounting - LH		86.30	7

Con't Page 3 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SLJ 8719 M
Our Ref : 022384

Page : 3

No. : 32627

1 pc engine mounting - rear		128.65	?
2 pcs rear shock absorber (LH/RH)	@ S\$285.80	571.60	?
2 pcs rear bearing (LH/RH)	@ S\$ 98.40	196.80	?
1 pc rear axle		890.40	?
1 pc rear bumper		<u>Bu 1,103.20</u>	✓

16,565.89
Less 15% : -2,484.88

14,081.01

2 pcs RH headlamp high beam bulb	@ S\$ 20.00
2 pcs RH headlamp light bulb	@ S\$ 15.00
2 pcs RH headlamp signal bulb	@ S\$ 15.00
1 pc radiator coolant	
1 pc RH front tyre	
1 pc RH front sport rim	

OHMY	40.00	sn	✓
na	30.00	sn	✓
na	30.00	sn	✓
	48.00	sn	?
pu	180.00	sn	X
pu	540.00	sn	X

To tow accident vehicle to workshop
by normal towing

60.00 ✓

To remove, cut out damaged parts,
panel beating, welding, align,

1,000.00 ✓

To dismantle and check front under-
carriages. To replace affected
portions.

300.00 ?

To conduct front wheel alignment
test.

80.00 ✓

To putty and respray on affected
portions.

1,200.00 1000

To focus headlamps. To check front
wiring and lighting operation.

30.00 200

Total : S\$17,619.01

Singapore Dollars Seventeen Thousand Six Hundred
and Nineteen and Cent One Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/11/2022 18:12 (SGT)
Reported by	Both
Date of Accident	01/11/2022 14:45 (SGT)
Exact Location of Accident	Yishun Street 22, Singapore
Additional Location Information	YISHUN STREET 22
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJP2542L

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NEO SAY BENG
NRIC No	SXXXX551F
Email Address	NEOS0021@E.NTU.EDU.SG
Mobile Phone No	(Phone) +65-88850518
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Suzuki
Model	Swift
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1328

INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10629261R01

DRIVER

Name of Driver	NEO SAY BENG
NRIC No	SXXXX551F
Date Of Birth	08/04/1961
Occupation	Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



A: SJP 2542L

B: SLJ 8719M

Hit by B & push up the kerb